

BRB (Residuary) Ltd

VAR9/830

03/04 BE4 Assessment Programme

**ASSESSMENT AND INSPECTION
REPORT**

BE 4 1967 Assessment

Structure EBD/761

April 2004

Document control sheet

Form IP180/B

Client BRB (Residuary) Ltd
Project 03/04 BE4 Assessment Programme
Title Structure EBD/761

Job No J20308B

	Prepared by	Reviewed by	Approved by
ORIGINAL	NAME	NAME	NAME
DATE 1/7/04			
REVISION	NAME	NAME	NAME
DATE	SIGNATURE	SIGNATURE	SIGNATURE
REVISION	NAME	NAME	NAME
DATE	SIGNATURE	SIGNATURE	SIGNATURE
REVISION	NAME	NAME	NAME
DATE	SIGNATURE	SIGNATURE	SIGNATURE

This report, and information or advice which it contains is provided by JacobsGIBB Ltd solely for internal use and reliance by its Client in performance of JacobsGIBB Ltd's duties and liabilities under its contract with the Client. Any advice, opinions, or recommendations within this report should be read and relied upon only in the context of the report as a whole. The advice and opinions in this report are based upon the information made available to JacobsGIBB Ltd at the date of this report and on current UK standards, codes, technology and construction practices as at the date of this report. Following final delivery of this report to the Client JacobsGIBB Ltd will have no further obligations or duty to advise the Client on any matters, including development affecting the information or advice provided in this report. This report has been prepared by JacobsGIBB Ltd in their professional capacity as Consulting Engineers. The contents of the report do not, in any way, purport to include any manner of legal advice or opinion. This report is prepared in accordance with the terms and conditions of JacobsGIBB Ltd's contract with the Client. Regard should be had to those terms and conditions when considering and/or placing any reliance on this report. Should the Client wish to release this report to a Third Party for that party's reliance, JacobsGIBB Ltd may, at its discretion, agree to such release provided that:

- (a) JacobsGIBB Ltd's written agreement is obtained prior to such release, and
- (b) By release of the report to the Third Party that Third Party does not acquire any rights, contractual or otherwise, whatsoever against JacobsGIBB Ltd and JacobsGIBB Ltd accordingly assume no duties, liabilities or obligations to that Third Party and
- (c) JacobsGIBB Ltd accepts no responsibility for any loss or damage incurred by the Client or for any conflict of JacobsGIBB Ltd's interests arising out of the Client's release of this report to the Third Party

JacobsGIBB Ltd

West Offices, City Business Centre
Station Rise, York
YO1 6HT, UK
Tel +44 (0)1904 524785
Fax +44 (0)1904 523040

Contact
Email

Our Ref 041581-NAR-J24110

Date 28 March 2006

BRB (Residuary) Ltd
Room C5
Hudson House
YORK
YO1 6HP

De

Structure EBD/761 (VAR9 830)

Bridge EBD/761 currently fails on jack arch details. The existing archive sketch states that the jack arch thickness is 6"

Jacobs have reviewed the site levels and trial pit results. The trial pit uncovered a concrete backing to the jack arch, the concrete was not broken out so the jack arch extrados was not located. The thickness of the jack arch and concrete was calculated as 177mm (6 97") by a closed levelling circuit.

The arch barrel thickness (including concrete fill above) is deemed to be compliant if it is greater than 220mm in accordance with the approved pro forma for empirical assessment for jack arches.

Therefore the jack arch and concrete thickness at EBD 761 is non compliant.

Two options are available to progress the assessment result.

1. Carry out another SI to determine the thickness of the jack arch by coring and check the thickness in a number of locations to ensure a representative thickness is obtained. (Cost is likely to be £3000 -£4000 but would still need a tie-bar installation scheme)
2. Implement a structural backing and tie-bar scheme to strengthen the bridge to BE4 loading (Cost is likely to be approx £25,000)

Contents

1	General Description and Structural Details	1-1
1 1	Location	1-1
1 2	Construction type	1-1
2	Existing Information Search	2-1
2 1	Information Used to Form Assessment	2-1
2 2	Ground Investigation/ SI Results	2-1
2 3	Existing Drawings	2-1
2 4	Services Search	2-1
3	Structure Condition	3-1
3 1	External Girders	3-1
3 2	Internal Girders	3-1
3 3	Jack arches	3-1
3 4	Tie Bars	3-1
3 5	Abutments	3-1
3 6	Wingwalls	3-2
3 7	Parapets	3-2
3 8	Carriageway	3-2
3.9	Formation	3-2

Appendix A - Photographs
 Appendix B - Form AA
 Appendix C - Summary of BE4 Results and Recommendations
 Appendix D - Form BA and BAA
 Appendix E - Site Investigation Results
 Appendix F - Services Search
 Appendix G - Calculations

1**General Description and Structural Details****1.1 Location**

Structure EBD/761 is located on the Ellan to Bodam disused railway line at a Grid Reference of NJ992319. The structure is named Ackmakoy and carries a public road.

1.2 Construction type

The structure is a single span cast iron jack arch. The deck comprises of 6 No longitudinal girders with transverse spanning brick jack arches. The abutments, wingwalls and pilaster are constructed from masonry, the parapet is of metallic construction.

2 Existing Information Search

2.1 Information Used to Form Assessment

The following documents were provided by BRB (Residuary) Ltd

Historical bridge assessment report

Visual and detailed examination reports

2.2 Ground Investigation/ SI Results

An inspection pit was excavated on the bridge deck in the east verge

The excavation determined the depth and composition of the fill and the condition and level of the top flange of the internal girder

See appendix E for the site investigation results

2.3 Existing Drawings

Existing sketches were provided

2.4 Services Search

A comprehensive search of existing services has been carried out in the vicinity of the bridge. This involved contacting the Statutory Undertakers who may own plant in the area.

Full details of all the organisations contacted and their responses can be found in Appendix F

Unfortunately responses from Scottish Water were not obtained at this stage

3

Structure Condition**3.1 External Girders**

The external girders are generally in good condition, however, a complete loss of paint system is apparent over the bottom flange. The majority of the paint system is still intact over the web and top flange. The bottom flange shows minor corrosion with a section loss of up to 1mm in thickness. The web, web stiffeners and top flange are all in good condition with no section loss.

3.2 Internal Girders

The internal girders have only their bottom flanges visible, these are generally in good condition with only minor corrosion (approximately 1mm loss of thickness section). There is a complete loss of paint system over the bottom flanges and the girders are slightly damp with leaching apparent.

3.3 Jack arches

The structure comprises 5 jack arch bays. The arches are generally in good condition with no major open joints or spalling. A transverse fracture can be found near the south abutment in the west external bay, the fracture is approximately 0.5m long and is open to a width of approximately 5mm. The fracture indicates that the external girder is moving outwards slightly and thus spreading the arch.

3.4 Tie Bars

The structure comprises of three lines of tie bars. The bars are situated approximately 100mm above the bottom flange level. The bars are generally either severely corroded or completely missing in all the bays.

3.5 Abutments**3.5.1 North Abutment**

The north abutment is constructed of masonry and is found to be in good condition with no open joints or spalling. Three joints have purposely been left open at ground level. These joints are 30mm wide and up to 1.5m in depth. The wall is generally dry apart from the north east side which is slightly damp.

3.5.2 South Abutment

The south abutment is also in good condition with no open joints or spalling. Again three joints are open at ground level to the same width and depth of the north abutment. Joint fractures are apparent under each external girder indicating lateral movement of the external girders due to the lack of horizontal restraint. The fractures are open to approximately 10mm and are approximately 2m long.

The south abutment has pins inserted horizontally behind and beneath the external girder, their purpose is unknown.

3.6 Wingwalls

3.6.1 North West Wingwall

The north west wingwall is in good condition with minor open joints and no vegetation growth over the face

3.6.2 North East Wingwall

The north east wingwall is in good condition, no open joints or spalling and no vegetation growth over the face

3.6.3 South East Wingwall

The south east wingwall is generally in good condition with minor open joints. The wall has minor vegetation growth over its face.

3.6.4 South West Wingwall

The south west wingwall is also in good condition with minor open joints. The wall has minor vegetation growth over its face

3.7 Parapets

Both inside and outside faces of the parapets are in good condition but are found to have a complete loss of paint system. The four pilasters are also in good condition with their coping stones in place. Wooden fencing is located adjacent to each pilaster, this has collapsed to the east side of the bridge, the west side has been recently replaced.

3.8 Carriageway

The bridge carries a public road, which is found to be in good condition with no surface fractures, two verges are also located on either side of the road

3.9 Formation

The old disused railway formation has now been grassed over and is generally clear from vegetation. To the east and west of the bridge the formation is in a steep sided cutting

Appendix A - Photographs



1

View of carriageway and verges looking south



2

Broken fence adjacent to south east pilaster



3

West Elevation



4

East Edge Girder



5

Jack Arches




6

Edge jack arch bay and broken tie bars



7

South Abutment



8

North Abutment



9

North West Wingwall



10

South East Wingwall



11

South West Wingwall



12

North East Wingwall



13

Trial pit in east verge



14

Trial pit reinstatement

Appendix B - Form AA

FORM 'AA' (BRIDGES)**GC/TP0356**ELR/ Bridge No **EBD 761 (VAR9/830)**

Appendix 4

Issue: 1

Revision B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT

Bridge/Line Name Auchmacoy bridge**ELR/Bridge No.** EBD/761**Brief Description of Existing Bridge:**

(a) Span Arrangement

Single square span of 4 540

(b) Superstructure Type

Cast iron girder overbridge with transverse spanning brick jack arches and metallic parapet

(c) Substructure Type

Large coursed masonry abutments and wingwalls

(d) Details of any Special Features

Internal and edge beams are of different section

Assessment Criteria

(a) Loadings and Speed

Dead loads and section sizes shall be determined from site measurements and existing drawings. Vehicle loading obtained from and applied in accordance with BE4 Standard BE4 loading representative of 24 ton vehicles will be assessed.

(b) Codes to be used

BE4 "The assessment of construction and use vehicles" Ministry of Transport, 1967
With Amendments to 1969

(c) Proposed Method of Structural Analysis

BE4/1967 will be used for the assessment

The longitudinal girders will be treated as simply supported and assessed in accordance with BE4 Part II Section 3

The jack arches and associated ties shall be assessed using an empirical assessment of brick, masonry and concrete jack arches and associated ties. This method is a departure from standard and is outlined by RPL in the VAR-671 BE4 Assessment letter dated 16 October 2001.

Measured dimensions taken from the site investigation and existing drawings are to be used in the BE4 calculations.

(d) Details of any Special Requirements

FORM 'AA' (BRIDGES)

GC/TP0356

ELR/ Bridge No . EBD 761 (VAR9/830)

Appendix 4

Issue 1

Revision B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT

None

Senior Civil Engineer's Comments

None.

Proposed Category for Independent Check .

Superstructure

I

Substructure

I

Name Of Checker Suggested If Cat 2 Or 3

Category 1

The above assessment, with amendments shown, is approved in principle

Signed

Title

Date

*CIVIL ENGINEER**16/4/04*

Category 2 and 3

The above assessment, with amendments shown, is approved in principle

Signed

Title

Date

Signed

Title

Date

Appendix C - Summary of BE4 Results and Recommendations**Summary of calculations**

The internal and external girders were assessed to BE4 and they were found to PASS the assessment

Considering an empirical assessment of the edge beams and transverse ties, a 24 ton gross vehicle weight capacity has been found if new (or extra) tie rods are installed and the barrel thickness is made compliant

The jack arches are not compliant with the minimum arch barrel thickness stated in the empirical assessment method

Therefore, the capacity of the structure is 24 tons if extra tie rods are installed

Recommendations

Jacobs recommends that additional tie bars are to be placed on the structure for additional lateral restraint. The arches can be saddled with 50mm or more of concrete to meet the minimum barrel thickness requirements

Appendix D - Form BA and BAA

FORM 'BA' (BRIDGES)**GC/TP0356**

ELR/ Bridge No ...EBD 761 (VAR9/830)

Appendix 4

Issue: 1

Revision A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECK**Assessment Group - JacobsGIBB Ltd****Bridge/Line Name – Auchmacoy Bridge****Category Of Check - 1****ELR/ Bridge No. – EBD / 761**

I certify that reasonable professional skill and care have been used in the assessment of the above structure with a view to securing that

- (1) It has been assessed in accordance with the Approval in Principle (where appropriate) as recorded on Form AA approved on 16/06/04
- (2) It has been checked for compliance with the following principal British Standards, Codes of Practice, BRB (Residuary) Limited Technical notes and Assessment standards

BE4 " The assessment of construction and use vehicles" Ministry of Transport, 1967 With Amendments to 1969

List any departures from the above, and additional methods or criteria adopted, with reference and justification for their acceptance (commenting on the results if appropriate)

... ..

Category 1

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible

Category 2 and 3 (Note Category 1 Check Must Also Be Signed)

(a) Assessment

Name

Signature

Date

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers

FORM 'BAA' (BRIDGES)**GC/TP0356**

ELR/ Bridge No ...EBD 761 (VAR9/830)

Appendix 4

Issue 1

Revision A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECK**Notification of Assessment Check****Assessment Group – JacobsGIBB Ltd****Bridge Name/Road.No. – Auchmacoy Bridge****Line Name – Ellan to Bodam Branch Line****ELR Code/Structure No. – EBD / 761**

The above bridge has been assessed and checked in accordance with Standards which are listed on the appended Form BA. A summary of the results of the assessment in terms of capacity and restrictions is as follows -

STATEMENT OF CAPACITY

24 Tons if extra tie rods are installed and the arch barrels are strengthened

Critical member/s Tie bars / jack arch barrels

Recommended Loading Restrictions

A restriction appropriate to the above is to be implemented

Description of Structural Deficiencies and Recommended Strengthening

Jacobs recommends that additional tie bars are to be placed on the structure to provide additional lateral restraint and that the arch barrels are saddled with at least 50mm structural concrete so they comply with the minimum thickness requirement

Date

25/6/04

Assessor

1/7/04

Assessment Checker

12/7/04

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/This Certificate Is Accepted By ... 

FORM 'BA' (BRIDGES)**GC/TP0356**

ELR/ Bridge No ...EBD 761 (VAR9/830)

Appendix: 4

Issue: 1

Revision: A (Feb 1993)


CERTIFICATION FOR ASSESSMENT CHECKTo Whom Assessor/
Checker Is Responsible(b) CheckNameSignatureDate

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible

This Certificate Is Accepted By



Appendix E - Site Investigation Results




STRUCTURAL SOILS

TRIAL PIT LOG

Contract BE4 BRIDGES - EBD/761		Client JACOBS		Trialpit No TP 01	
Job No 36206	Date 12.02.04	Ground Level	Co-Ordinates	Sheet 1 of 1	

Samples and In-situ Tests				Water	Description of Strata	Depth (Thickness)	Legend
Depth	No	Type	Results				
					Topsoil	0.15	
					MADE GROUND Brown slightly silty very sandy angular to sub angular fine to coarse GRAVEL of granite and assorted volcanic rocks Occasional cobbles.	0.35	
					MADE GROUND Black bitumen sealer 0.37m - steel top flange.	0.37	




General Remarks

- 1 EASE OF EXCAVATION EASY
- 2 SIMILARITY OF FACES ALL SIMILAR (concrete fill noted over jack arch, concrete not excavated)
- 3 STABILITY OF FACES ALL STABLE
- 4 WATER NONE ENCOUNTERED

All dimensions in metres Scale 1:25	Method Inspection pit	Logged By MD	Checked By
---	---------------------------------	------------------------	------------

Appendix F - Services Search

NJ9831SW
Map not held
by Transco








NK0031SW
Map not held by Transco

Diagram illustrating the structure of the 1000 Genomes Project data. The populations are represented by colored bars:

- LP MAINS (Red)
- MP MAINS (Blue)
- IP MAINS (Green)
- LHP MAINS (Orange)
- NHP MAINS (Purple)
- LAS (Pink)
- GTs (Light Blue)
- SSSIs (Light Green)

Some examples of Plant Items:

Valve		Depth of Cover		Syphon		Diameter Change		Material Change	
-------	--	----------------	---	--------	---	-----------------	---	-----------------	---

Glasgow *ED/761*

This plan is reproduced from or based on the OS map by Transco plc, with the sanction of the controller of HM Stationery Office.
Crown Copyright Reserved.

Atkins Telecoms
PO Box 290
220 Aztec West
Park Avenue
Almondsbury
BRISTOL BS32 4SY

Tel 01454 288808
Fax 0870 2403012
Email osm.enquiries@atkinsglobal.com

Jacobs Gibb Ltd
WEST OFFICES, CITY BUSINESS CENTRE
STATION RISE
YORK
YO1 6HT

Our Ref NRSWA/544/158498
YourRef 36890-B220-J20308B-DT1

FAO

Date 23 January 2004

Dear Sirs,

New Roads and Street Works Act 1991
32 Plant Enquiry re Highway Land only - Plant Affected

Thank you for your enquiry regarding works at PAL/3, for proposed WORKS

Cable and Wireless UK have apparatus in the vicinity of your proposed scheme. We have enclosed plans showing the approximate position of the apparatus, please note the disclaimer on the plans

telecoms

Atkins Telecoms
220 Aztec West
Park Avenue
Bristol
Avon BS32 4SY
England

Telephone +44 (0)1454 201999
Fax +44 (0)1454 628799

telecoms@atkinsglobal.com
www.atkinsglobal.com/telecoms

THE OTHER SITES IN THE
same enquiry are NOT
AFFECTED.

with compliments

Yours Faithfully,

OSM, U.K. and Ireland
Acting as agent for and on behalf of Cable and Wireless UK

Please note To enable us to process your application as quickly as possible, please ensure that you include a post code and/or an Ordnance Survey Grid Reference. Thank you for your co-operation

RECEIVED		DT	
26 JAN 2004			
ACTION	SIGN	INFO	SIGN
FILE REF			

Issue 2 00 17 September 2002

The ntl Tower
Jagger Lane
Emley Moor
Huddersfield
West Yorkshire
HD8 9LQ

www.ntl.com

t 01924 508000
f 01924 508939
e firstname.surname
@ntl.com

Jacobs Gibb
West Offices
City Business Centre
Station Rise, York
YO1 6HT

ITEM No.		37019	
REVIEWER		DT	
5007 10/1/07		87	
ACTION	SIGN	INFO	SIGN
REPLY DATE			
FILE REF			



16 January 2004

RESPONSE TO YOUR REQUEST FOR PLANT LOCATION INFORMATION
HEALTH & SAFETY AT WORK ACT 1974 HS (G) 47
NEW ROADS AND STREET WORKS ACT 1991 SECTION 79 (3)

A O

Ref 105175

Ref 36911-B220-J20308B-DT1

Location AGB/3, AGB/5, DA52/20,
END/714, EBD/761, FHB/1043 +
ELW/9

AGB/761

Dear Sir or Madam

In response to your notice for the above reference we can confirm that, at present, we do not have any apparatus at the locations indicated and we do not propose any work in this area in the near future

If we can be of any further assistance, please do not hesitate to contact us on 0870 0130045 or fax on 01924 508939

Yours Faithfully

ntl Plant Protection

ntl endeavour to respond to your enquiries within a short timescale. Please ensure that OS grid reference numbers and location plans are provided, along with the correct Postal address and fax number

ntl Business Limited
Registered Office:
ntl House
Bartley Wood Business Park
Hook
Hampshire
RG27 9UP

Registered in
England and Wales
number 3076722

Mapping Services (North)

Inveralmond House,

200 DunkeId Road

Per th

PH1 3AQ

15/12/2003

If you require further information
please call the District number on
the location plan

EBD/701

ФМВ/1043

GIBB - York			
ITEM NO		36760	
REVIEWER		DT	
19 DEC 2003			
ACTION	SIGN	INFO	SIGN

West Offices
City Business Centre
Station Rise
YORK
YO1 6HT

Dear Sir/Madam

FHB/1043, EBD/761

In response to your enquiry of 11 DECEMBER 2003 regarding the location of electricity cables and equipment at the above, copies of our Record Plans are enclosed

The plans show the positions and normal depths for the buried cables etc when they were installed. It must be stressed, however, that alterations to road alignments, surface levels and buildings may have been made subsequent to the records being taken. If you find plant or cables that are not marked or are incorrectly marked, then you are required to contact us as soon as possible to give us the opportunity to amend our records.

It has not been possible to transfer our mains records onto your plan. Please note that the plans supplied are based on the location/map information supplied by yourselves and, therefore, YOU MUST SATISFY YOURSELF THAT OUR PLANS SUPPLIED ADEQUATELY COVER THE AREA THAT YOU REQUIRE.

Please note that these records only show plant owned by Scottish and Southern Energy plc. There may be other privately owned plant in the area, which is outside the control of Scottish and Southern Energy Electric plc. You should check with the Local Authority, National Grid Co., Department of the Environment, other Regional Electricity companies etc. before proceeding.

Avoidance of DANGER from BURIED CABLES

For more information, consult the Health & Safety Executive's booklet HS(G) 47 - obtainable from the HMSO. Guidance notes are contained in Scottish and Southern Energy's 'Watch-It' leaflet, which sets out various do's and don'ts when digging near buried cables.

I would particularly draw your attention to the need to take trial holes to determine the exact position and depth of cables to avoid the risk of injury to staff or damage to the cables

Where our Record plans indicate the presence of cables with a voltage exceeding 11,000 volts then you are advised to contact our Local Depot section on the above telephone number before commencing any excavations within the vicinity of these cables

Avoidance of DANGER from OVERHEAD LINES

For more information, consult the Health and Safety Guidance Note GS.6 obtainable from HMSO
Scottish and Southern Energy's 'Watch-It' leaflet outlines the precautions to be taken.

If in any doubt about the safety of working in the vicinity of overhead lines, please do not hesitate to contact our Local Depot at the above number


Cable Records – Service Connections

The location of service cables to individual properties, street lighting, traffic signs, telephone kiosks etc installed prior to the introduction of the Electricity Supply Regulation 1988 dated 1st October 1988 are not shown on the enclosed plans but details are available from our local depot NORTH EAST DISTRICT tel 01224 287600

General Advice


- a) Please ensure, where appropriate, that your CONTRACTORS have a copy of this letter and the enclosed plan(s)
- b) Please note that the cost of any repairs or claims against Scottish and Southern Energy as a result of your works will be invoiced to you or your contractor
- c) Scottish and Southern Energy retains the right to its property, including disconnected cables and recoverable materials

Should you require further information, please do not hesitate to contact me on the above telephone number.



Enclosures

- | | |
|--|---|
| - Mains Record Plans ALL Voltages | Y |
| - Mains Record Plans Gas | N |
| - 'Watch-It' for working near O/H lines | N |
| - 'Watch-It' for digging near U/G cables | N |
| - Other | |



1

Date AS POSTMARK

National Notice Handling Centre
PP 404B, Telecom House,
Trinity Street,
Hanley,
Stoke-on-Trent,
ST1 5ND

Freephone 0800 800 865

NR & SW ACT 1991 - PROPOSED WORKS AT :- AYL/2,DAK/86, KBE16 ETC

Enclosed are copies of our drawing marked up to show the approximate locations of BT apparatus which is present in the immediate vicinity of your works. It is intended for general guidance only. No guarantee is given of its accuracy.

It should not be relied upon in the event of excavations or other works made near to British Telecommunications plc apparatus which may exist at various depths and may deviate from the marked route


To avoid damage it is recommended that mechanical excavators or borers are not used within 600mm of British Telecommunications plc plant. If scaffolding is erected, please ensure that our equipment is not enclosed, blocked, covered or otherwise obstructed by the scaffolding.

In the event of BT apparatus being in the area of works we recommend that your plant/vehicle crossing is either resited, or apply for a budget estimate by submitting detailed plans to the above address, these will be forwarded to the appropriate department for their comments

***For free on site assistance prior to commencement of work please contact our Plant Protection Service by dialling 0800 9173993, or dial 100 and ask for "Freephone Dial before you dig" or Email DBYD@bt.com
We require 7 working days notice.***

Please ensure you quote our reference on any future correspondence.

GIBB - York			
ITEM No		36761	
REVIEWER		DT	
19 DEC 2003			
ACTION	SIGN	INFO	SIGN
REPLY DATE			



IMPORTANT WARNING
Information regarding the location of BT apparatus is given for your assistance and is intended for general guidance only. No guarantee is given of its accuracy. It should not be relied upon in the event of excavations or other works being made near to BT apparatus which may exist at various depths and may deviate from the marked route.

Reproduced from an OS map by permission of Controller HMSO. Crown Copyright Reserved, with British Telecommunications plc data added. Copyright British Telecommunications plc.

PLANT INFORMATION REPLY

British Telecommunications plc

Notes:

399200,831900
FBD/761

If more information is required please submit larger scale plans

Appendix G - Calculations

Project Title		VAR 9/830 BE4 1967 ASSESSMENTS		Sheet No		1					
Subject		EBD/761		Calc No							
Job No		J20308B-1142		File							
Made by		JLW		Date		Revised		Date			
Checked by		JLR		Date		1/7/04		Checked by		Date	

DEAD LOADS

Scale

$$\text{EXTERNAL GIRDER - SECTIONAL AREA} = 27616 \text{ mm}^2$$

$$= 0.028 \text{ m}^2$$

BE4, Page 4

$$\text{CAST IRON} = 450 \text{ lbs/ft}^3 = 70.69 \text{ KN/m}^3$$

$$\therefore 0.028 \times 70.69 = \underline{1.98 \text{ KN/m}}$$


Scale

$$\text{INTERNAL GIRDER - SECTIONAL AREA} = 29638 \text{ mm}^2$$

$$= 0.0296 \text{ m}^2$$

$$\therefore 0.0296 \times 70.69 = \underline{2.1 \text{ KN/m}}$$

JACK ARCH



- 70mm
- 222mm
- 25mm
- 152mm
- 212mm
- 32mm
- Bottom
- FLANGE

$$R_1 = \frac{212}{2} + \frac{875^2}{8 \times 212} = 106 + 451.43 = \underline{557.43 \text{ mm}} \quad \checkmark$$

$$R_2 = R_1 + \text{JACK ARCH} = 557.43 + 152.4 = \underline{709.83 \text{ mm}} \quad \checkmark$$

Title		Sheet No 2	
		Calc No	
		File	
by	Date	Revised	Date
ed by JFR.	Date 1/7/04	Checked by	Date

- AREA OF JACK ARCH BETWEEN RADIAL LINES

$$= \tan \theta = \frac{(875/2)}{(557.43 - 212)} = \frac{437.5}{345.43} = 1.266537$$


$$\therefore \theta = 51.707^\circ$$

$$\text{Area} = \pi (R_2^2 - R_1^2) \frac{\theta}{180} = 3.14159 (709.83^2 - 557.43^2) \frac{51.707}{180}$$

$$= 3.14159 \times 193130.424 \times 0.2873$$

$$\text{Area} = 174315 \text{ mm}^2$$

- AREA OF JACK ARCH OVER BOTTOM FLANGE



$$\beta = 90 - \theta$$

$$= 90 - 51.707$$

$$= 38.29^\circ$$

$$\therefore \cos \beta = 0.7849$$

$$\sin \beta = 0.6196$$

$$\tan \beta = 0.7895$$

Project Title		Sheet No 2	
Subject		Calc No	
Job No		File	
Made by	Date	Revised	Date
Checked by JLR	Date 1/7/04	Checked by	Date

AREA 1

$$= (152 \times 0.7849) \times (152 \times 0.6196) \times 0.5$$

$$= 0.5 \times 152^2 \times 0.7849 \times 0.6196$$

$$\underline{\text{AREA 1} = 5618 \text{ mm}^2}$$

AREA 2

$$= \frac{C \cdot e}{2} = \frac{C^2}{2 \tan \beta} = \left(\frac{E - e}{2} - 152 \cos \beta \right)^2 \times \frac{1}{2 \tan \beta}$$

$$\therefore \left(\left(\frac{381 - 32}{2} \right) - 152 \times 0.7849 \right)^2 \times \frac{1}{2 \times 0.7895}$$

$$\therefore \frac{(174.5 - 119.3)^2}{1.579}$$

$$\underline{\text{AREA 2} = 1930 \text{ mm}^2}$$

AREA 3

$$C = \left(\frac{E - e}{2} \right) - 152 \times 0.7849 = 174.5 - 119.3$$

$$C = 55.2 \text{ mm}$$

$$\text{AREA 3} = (b - e)C = \left(152 \sin \beta - \frac{C}{\tan \beta} \right) C$$

$$= \left(94.18 - \frac{55.2}{0.7895} \right) \times 55.2$$

$$\underline{\text{AREA 3} = 1339 \text{ mm}^2}$$

Project Title		Sheet No 4	
Subject		Calc No	
Job No	File		
Made by	Date	Revised	Date
Checked by <i>gxr</i>	Date 1/7/04	Checked by	Date

TOTAL AREA OF JACK ARCH

$$\begin{aligned}
 &= 174315 + (2 \times (\text{AREA 1} + 2 + 3)) \\
 &= 174315 + (2 \times 8887) \\
 &= 192089 \text{ mm}^2 = \underline{0.19 \text{ m}^2} \quad \checkmark
 \end{aligned}$$

$$\text{MASONRY} = 144 \text{ kg/ft}^3 = 22.62 \text{ KN/m}^3$$

$$\therefore 0.19 \times 22.62 = \underline{4.3 \text{ KN/m}} \quad \checkmark$$

FILL - CONCRETE

$$\begin{aligned}
 &= 1257.3 \times (212 + 152 + 25) - \text{AREA OF JACK ARCH} \\
 &\quad - \text{ARCH SEGMENT} - \text{AREA OF INTERNAL GIRDER} \\
 &\quad \text{UP TO CONCRETE LEVEL FROM TOP OF BOTTOM FLANGE.}
 \end{aligned}$$

$$\begin{aligned}
 \therefore & (1257.3 \times 389) - 192089 - \left[\pi \frac{557.4^2 \times 51.707}{180} - (557.4 - 212) \frac{875}{2} \right] \\
 & - (389 \times 32)
 \end{aligned}$$

$$\begin{aligned}
 \therefore & 489090 - (192089 + 129453 + 12448) \\
 & = 155100 \text{ mm}^2 = \underline{0.155 \text{ m}^2} \quad \checkmark
 \end{aligned}$$

$$\text{CONCRETE} = 150 \text{ kg/ft}^3 = 23.56 \text{ KN/m}^3 \quad \checkmark$$

$$\therefore 0.155 \times 23.56 = \underline{3.65 \text{ KN/m}} \quad \checkmark$$

Project Title		Sheet No 5	
Subject		Calc No	
Job No		File	
Made by	Date	Revised	Date
Checked by <i>JLR</i>	Date 1/7/04	Checked by	Date

FILL - SOIL & STONES

AREA - AREA OF INTERNAL GIRDER PROTRUDING FROM THE CONCRETE.

$$\begin{aligned}
 & \therefore 1257.3 \times 212 - ((152.4 \times 32) + (4 \times 2 \times 32)) \\
 & \quad 279121 - 5027 = 274093 \text{ mm}^2 \\
 & = 266548 - 5011 \\
 & = 261537 \text{ mm}^2 = \underline{0.26 \text{ m}^2}
 \end{aligned}$$

222 mm at P.1
Wider Flange
4.7 = (1'-6") - (2 x 1/4") 212 - 152 =

$$\text{EARTH, SAND, GRAVEL ETC.} = 135 \text{ lbs/ft}^3 = 21.2 \text{ KN/m}^3$$

$$\therefore 0.26 \times 21.2 = \underline{5.5 \text{ KN/m}} \quad (= 5.8 \text{ KN/m})$$

SURFACING

$$1257.3 \times 70 = 88011 \text{ mm}^2 = \underline{0.09 \text{ m}^2}$$

$$\text{MACADAM} = 144 \text{ lbs/ft}^3 = 22.62 \text{ KN/m}^3$$

$$\therefore 0.09 \times 22.62 = \underline{2.03 \text{ KN/m}}$$

TOTAL DEAD LOAD - INTERNAL GIRDERS

P.1	GIRDER S/W	= 2.1 KN/m	✓
P.4	JACK ARCH	= 4.3 KN/m	✓
P.4	CONCRETE	= 3.65 KN/m	✓
P.5	FILL	= 5.5 KN/m	
P.5	SURFACING	= 2.03 KN/m	✓
	TOTAL	= <u>17.6 KN/m</u>	✓

accept

Project Title		Sheet No 6	
Subject		Calc No	
Job No		File	
Made by	Date	Revised	Date
Checked by <i>JLR</i>	Date 1/7/04	Checked by	Date

Ref to
SITE NOTES

PARAPET - CAST IRON PLATE

$$1120 \times 56 = 62720 \text{ mm}^2 = 0.063 \text{ m}^2$$

$$\text{CAST IRON} = 450 \text{ kN/m}^3 = 70.69 \text{ kN/m}^3$$

$$\therefore 0.063 \times 70.69 = 4.45 \text{ kN/m}$$

✓

VERGE - FILL IN PLACE OF SURFACING

$$\frac{0.09}{2} = 0.045 \text{ m}^2$$

✓

$$\text{EARTH, SAND GRAVEL ETC.} = 135 \text{ kN/m}^3 = 21.2 \text{ kN/m}^3$$

$$\therefore 0.045 \times 21.2 = 0.95 \text{ kN/m}$$

✓

TOTAL DEAD LOAD - EXTERNAL GIRDER

$$\text{GIRDER S/W} = 1.98 \text{ kN/m}$$

✓

$$\text{JACK ARCH } 1/2 = 2.15 \text{ kN/m}$$

✓

$$\text{CONCRETE } 1/2 = 1.83 \text{ kN/m}$$

✓

$$\text{FILL } 1/2 = 2.75 \text{ kN/m}$$

✓

$$\text{PARAPET} = 4.45 \text{ kN/m}$$

✓

$$\text{VERGE} = 0.95 \text{ kN/m}$$

✓

$$\text{TOTAL} = 14.11 \text{ kN/m}$$

✓

CALCULATION SHEET

Sheet No 1

Project Title VAR9-830 BE4

Assessment EBD 761

Job No J20308B-1142

Made by JCW

Checked by *JJR*

Date 16/12/03

Date. *1/1/04*

Summary of calculations

External girders

	Dead load moment	12 59 tonft
	Moment of resistance for live load	29 83 tonft
	M / K =	69 37 tonft
Graph 5	Assessed capacity =	24 tons Gross Vehicle Weight

Internal girders

	Dead load moment	17 58 tonft
	Moment of resistance for live load	45 31 tonft
	M / K =	138 13 tonft
Graph 5	Assessed capacity =	24 tons Gross Vehicle Weight

External girders - Empirical Assessment

Fails, due to heavily corroded tie bars

CALCULATION SHEET

Sheet No. 2

Project Title VAR9-830 BE4

Assessment EBD 761

Job No J20308B-1142


Made by: JCW

Checked by *JRW*

Date: 16/12/03

Date: 1/7/04

Assessment of Longitudinal members



Parapet Width $P_w = 13\text{mm}$

Verge Width $V_w = 1100\text{mm}$

BE4 Part 1
302

Line of Nearside
Wheel (X) $X = 229\text{mm}$

External Girder to Nearside Wheel

$$\text{Dist}_{\text{wheel}} = \frac{P_w}{2} + V_w + X$$

$$\text{Dist}_{\text{wheel}} = 1335.5\text{mm}$$

Girder Spacing $G_s = 1257\text{mm}$ ✓

$$G_s < \text{Dist}_{\text{wheel}}$$

BE4 Part 2
301

Therefore nearside wheels of the vehicle train has another member between them and the edge member

Edge girder is not therefore subject to live loading ✓

CALCULATION SHEET

Sheet No 3

Project Title. VAR9-830 BE4

Assessment EBD 761

Job No. J20308B-1142

Made by JCW

Checked by *JPL*

Date 16/12/03

Date 1/7/04

External Girder Assessment

Dead Loads

From BD 21/97

Girder Self Weight $G_{sw} = 1.98 \frac{\text{kN}}{\text{m}}$ ✓

Jack Arch $JA_{sw} = 2.15 \frac{\text{kN}}{\text{m}}$ ✓

Concrete $C_{sw} = 1.83 \frac{\text{kN}}{\text{m}}$ ✓

Fill (soil & stones) $SS_{sw} = 2.75 \frac{\text{kN}}{\text{m}}$ ✓

C / Parapet $P_1 = 4.45 \frac{\text{kN}}{\text{m}}$ ✓

Verge $V_{sw} = 0.95 \frac{\text{kN}}{\text{m}}$

Total Loading

$$W_{total} = G_{sw} + JA_{sw} + C_{sw} + SS_{sw} + P_1 + V_{sw}$$

$$W_{total} = 14.11 \frac{\text{kN}}{\text{m}}$$

Dead Load Moment

BE4-Part 1-303a (iv)

Effective span where the beam rests directly on hard material and there are no bearing stiffeners

Clear Span $C_{span} = 4572 \text{ mm}$ ✓

Beam depth (at support) $B_{depth} = 508 \text{ mm}$ ✓

Span L = Clear Span + (2/3 x 1/4 x beam depth)

$$Span_L = C_{span} + \left[\left(\frac{2}{3} \right) \left(\frac{1}{4} \right) B_{depth} \right]$$

$$Span_L = 4657 \text{ mm}$$

Therefore $M_d = \frac{W_{total} (Span_L^2)}{8}$

$$M_d = 38.246 \text{ kNm}$$

$$M_d = 12.59 \text{ ton ft}$$
 ✓

CALCULATION SHEET

Sheet No 4

Project Title VAR9-830 BE4

Assessment EBD 761

Job No J20308B-1142

Made by: JCW

Checked by *JCR*

Date 16/12/03

Date 1/7/04

Stress due to dead load

$$I_{xx} = 0.96626 \times 10^9 \text{ mm}^4$$

$$I_{xx} = 2321.45 \text{ in}^4$$

$$y_{\text{bot}} = 222.29 \text{ mm}$$

$$y_{\text{bot}} = 8.75 \text{ in}$$

$$D = 508 \text{ mm}$$

$$D = 20 \text{ in}$$

$$y_{\text{top}} = D - y_{\text{bot}}$$

$$y_{\text{top}} = 285.71 \text{ mm}$$

$$y_{\text{top}} = 11.25 \text{ in}$$

Therefore $Z_{\text{bot}} = \frac{I_{xx}}{y_{\text{bot}}}$

$$Z_{\text{bot}} = 265.26 \text{ in}^3$$

$$Z_{\text{top}} = \frac{I_{xx}}{y_{\text{top}}}$$

$$Z_{\text{top}} = 206.38 \text{ in}^3$$

$$f_{d \text{ bot}} = \frac{M_d}{Z_{\text{bot}}}$$

$$f_{d \text{ bot}} = 0.57 \frac{\text{ton}}{\text{in}^2}$$

$$f_{d \text{ top}} = \frac{M_d}{Z_{\text{top}}}$$

$$f_{d \text{ top}} = 0.732 \frac{\text{ton}}{\text{in}^2}$$

External Girder Assessment

Stress due to dead load

Up to 3 tons/sq in tension the actual permissible tensile stress shall be based on the following ratio of dead to live load

BE4-Part 1-304c

$$5f_l + 2.2f_d = 8$$

Therefore

$$f_{l \text{ bot}} = \frac{\left(8 \frac{\text{ton}}{\text{in}^2} - 2.2f_{d \text{ bot}}\right)}{5}$$

$$f_{l \text{ bot}} = 1.349 \frac{\text{ton}}{\text{in}^2}$$

$$f_{l \text{ bot}} + f_{d \text{ bot}} = 1.92 \frac{\text{ton}}{\text{in}^2}$$

$$f_{l \text{ bot}} = \text{if} \left(f_{l \text{ bot}} + f_{d \text{ bot}} < 3 \frac{\text{ton}}{\text{in}^2}, f_{l \text{ bot}}, 3 \frac{\text{ton}}{\text{in}^2} - f_{d \text{ bot}} \right)$$

$$f_{l \text{ bot}} = 1.349 \frac{\text{ton}}{\text{in}^2}$$

$$f_{l \text{ top}} = \left(10 \frac{\text{ton}}{\text{in}^2} - f_{d \text{ top}} \right)$$

$$f_{l \text{ top}} = 9.27 \frac{\text{ton}}{\text{in}^2}$$

This is irrelevant if there is no live load to be considered.

$f_{d \text{ bot}} < 3 \text{ ton/in}^2$
ok.

CALCULATION SHEET

Sheet No 5

Project Title: VAR9-830 BE4

Assessment EBD 761

Job No J20308B-1142

Made by JCW

Checked by *JLR*

Date 16/12/03

Date 1/7/04

BE4-Part 2-301a(11)

$$M_{l\ bot} = f_{l\ bot} Z_{bot}$$

$$M_{l\ bot} = 29\ 83\ \text{ton ft}$$

$$M_{l\ top} = f_{l\ top} Z_{top}$$

$$M_{l\ top} = 159\ 39\ \text{ton ft}$$

$$M_l = (\text{if}(M_{l\ bot} < M_{l\ top}, M_{l\ bot}, M_{l\ top}))$$

$$M_l = 29\ 83\ \text{ton ft}$$

BE4-Part 2-301a(11)

$$\text{Girder Spacing} = G_s = 1257\ 3\ \text{mm}$$

$$G_s = 4\ 13\ \text{ft}$$

$$\text{Span} = \text{Span}_L \quad \text{Span} = 4657\ \text{mm}$$

$$\text{Span} = 15\ 28\ \text{ft}$$

$$\text{Carriageway width} = C_w = 3686\ \text{mm}$$

$$C_w = 12\ 09\ \text{ft}$$

BE4-Part 1-302a

If carriageway is less than 18', single lane applies

$$\text{Reduction factor} = K = 0\ 43$$

BE4-Part 2-301a(11)

$$\frac{M_l}{K} = 69\ 37\ \text{ton ft}$$

BE4-Part 2-301a(11) Graph 5

$$\text{Assessed capacity} = 24\ \text{tons Gross Vehicle Weight}$$

*Already stated that edge girder
is not subject to live loading*

CALCULATION SHEET

Sheet No. 6

Project Title VAR9-830 BE4

Assessment EBD 761

Job No J20308B-1142

Made by JCW

Checked by *JLR*

Date 16/12/03

Date 1/7/04

Internal Girder Assessment

Dead Loads

From BD 21/97

Girder Self Weight $G_{sw} = 2.1 \frac{\text{kN}}{\text{m}}$ ✓

Jack Arch $IA_{sw} = 4.3 \frac{\text{kN}}{\text{m}}$ ✓

Concrete $C_{sw} = 3.65 \frac{\text{kN}}{\text{m}}$ ✓

Fill (Soil & stones) $SS_{sw} = 5.5 \frac{\text{kN}}{\text{m}}$ 5.8 ✓

Carriageway $CA_{sw} = 2.03 \frac{\text{kN}}{\text{m}}$ ✓

Total Loading

$$W_{\text{total}} = G_{sw} + IA_{sw} + C_{sw} + SS_{sw} + CA_{sw}$$

$$W_{\text{total}} = 17.58 \frac{\text{kN}}{\text{m}}$$
 ✓

Dead Load Moment

BE4-Part 1-303a (iv)

Effective span where the beam rests directly on hard material and there are no bearing stiffeners

Clear Span $C_{\text{span}} = 4572 \text{ mm}$ ✓

Beam depth (at support) $B_{\text{depth}} = 457.2 \text{ mm}$

Span $L = \text{Clear Span} + (2/3 \times 1/4 \times \text{beam depth})$

$$\text{Span}_L = C_{\text{span}} + \left[\left(\frac{2}{3} \right) \left(\frac{1}{4} \right) B_{\text{depth}} \right]$$

$\text{Span}_L = 4648 \text{ mm}$ ✓

Therefore $M_d = \frac{W_{\text{total}} (\text{Span}_L^2)}{8}$ $M_d = 47.479 \text{ kNm}$ ✓

$M_d = 15.63 \text{ ton ft}$ ✓

CALCULATION SHEET

Sheet No 7

Project Title: VAR9-830 BE4
Assessment EBD 761
Job No J20308B-1142

Made by JCW
Checked by *JCR*

Date 16/12/03
Date: 1/7/04

Stress due to dead load

From BD 21/97

$$I_{xx} = 0.85258 \times 10^9 \text{ mm}^4 \quad \checkmark \quad I_{xx} = 2048.33 \text{ in}^4$$

$$y_{bot} = 176.04 \text{ mm} \quad y_{bot} = 6.93 \text{ in}$$

$$D = 457.2 \text{ mm} \quad \checkmark \quad D = 18 \text{ in}$$

$$y_{top} = D - y_{bot}$$

$$y_{top} = 281.16 \text{ mm} \quad y_{top} = 11.07 \text{ in}$$

Therefore

$$Z_{bot} = \frac{I_{xx}}{y_{bot}} \quad Z_{bot} = 295.54 \text{ in}^3 \quad \checkmark$$

$$Z_{top} = \frac{I_{xx}}{y_{top}} \quad Z_{top} = 185.05 \text{ in}^3$$

$$f_{d \text{ bot}} = \frac{M_d}{Z_{bot}} \quad f_{d \text{ bot}} = 0.635 \frac{\text{ton}}{\text{in}^2} \quad \checkmark$$

$$f_{d \text{ top}} = \frac{M_d}{Z_{top}} \quad f_{d \text{ top}} = 1.013 \frac{\text{ton}}{\text{in}^2}$$

Internal Girder Assessment

Stress due to dead load

Up to 3 tons/sq in tension the actual permissible tensile stress shall be based on the following ratio of dead to live load

BE4-Part 1-304c $5f_l + 2.2f_d = 8$

Therefore

$$f_{l \text{ bot}} = \frac{\left(8 \frac{\text{ton}}{\text{in}^2} - 2.2 f_{d \text{ bot}}\right)}{5}$$

$$f_{l \text{ bot}} = 1.321 \frac{\text{ton}}{\text{in}^2}$$

$$f_{l \text{ bot}} + f_{d \text{ bot}} = 1.96 \frac{\text{ton}}{\text{in}^2}$$

$$f_{l \text{ bot}} = \text{if} \left(f_{l \text{ bot}} + f_{d \text{ bot}} < 3 \frac{\text{ton}}{\text{in}^2}, f_{l \text{ bot}}, 3 \frac{\text{ton}}{\text{in}^2} - f_{d \text{ bot}} \right)$$

$$f_{l \text{ bot}} = 1.321 \frac{\text{ton}}{\text{in}^2} \quad \checkmark$$

$$f_{l \text{ top}} = \left(10 \frac{\text{ton}}{\text{in}^2} - f_{d \text{ top}} \right)$$

$$f_{l \text{ top}} = 8.99 \frac{\text{ton}}{\text{in}^2}$$

CALCULATION SHEET

Sheet No. 8

Project Title: VAR9-830 BE4

Assessment EBD 761

Job No: J20308B-1142

Made by: JCW

Checked by: *JAR*

Date: 16/12/03

Date: 1/7/04

BE4-Part 1-305b

The section modulus of the girder may be increased for live load by the factor D/d

D = Overall depth of deck less 3" for surfacing

d = Depth of girder at mid span

Overall depth of deck = $O_d = 713\text{mm}$

$D_1 = O_d - (3 \times 25.4)\text{mm}$ $D_1 = 636.8\text{mm}$

$d = D$ $d = 457.2\text{mm}$

$$\frac{D_1}{d} = 1.39$$

BE4-Part 2-301a(11)

$$M_{I\text{ bot}} = f_{I\text{ bot}} Z_{\text{bot}} \left(\frac{D_1}{d} \right)$$

$M_{I\text{ bot}} = 45.31\text{ ton ft}$

$$M_{I\text{ top}} = f_{I\text{ top}} Z_{\text{top}} \left(\frac{D_1}{d} \right)$$

$M_{I\text{ top}} = 193.01\text{ ton ft}$

$$M_I = \left(\text{if } (M_{I\text{ bot}} < M_{I\text{ top}}, M_{I\text{ bot}}, M_{I\text{ top}}) \right)$$

$M_I = 45.31\text{ ton ft}$

BE4-Part 2-301a(11)

Girder Spacing = $G_s = 1257.3\text{mm}$

$G_s = 4.13\text{ ft}$

Span = Span_L Span = 4657mm

Span = 15.28 ft

Carriageway width = $C_w = 3686\text{mm}$

$(C_w = 12.09\text{ ft})$ $13.4\text{ ft}?$

BE4-Part 1-302a

If carriageway is less than 18', single lane applies

see historic drawings
Does not affect result.

Reduction factor = $K = 0.328$

BE4-Part 2-301a(11)

$$\frac{M_I}{K} = 138.13\text{ ton ft}$$

BE4-Part 2-301a(11) Graph 5

Assessed capacity = 24 tons Gross Vehicle Weight

Office: 6114

Edge girder
Location: Properties of typical channel section

Properties of any plane section

The section is defined by coordinates of corner points taken in anti-clockwise order round the section. The cross section is kept to the left of the edge running from a previous point to the next point. The section is closed when the original point is specified again.

Coordinates of points in order:

Point 1	: X-coordinate	x(1)=0 mm
	: Y-coordinate	y(1)=0 mm
Point 2	: X-coordinate	x(2)=267 mm
	: Y-coordinate	y(2)=0 mm
Point 3	: X-coordinate	x(3)=267 mm
	: Y-coordinate	y(3)=32 mm
Point 4	: X-coordinate	x(4)=207 mm
	: Y-coordinate	y(4)=32 mm
Point 5	: X-coordinate	x(5)=207 mm
	: Y-coordinate	y(5)=476 mm
Point 6	: X-coordinate	x(6)=267 mm
	: Y-coordinate	y(6)=476 mm
Point 7	: X-coordinate	x(7)=267 mm
	: Y-coordinate	y(7)=508 mm
Point 8	: X-coordinate	x(8)=115 mm
	: Y-coordinate	y(8)=508 mm
Point 9	: X-coordinate	x(9)=115 mm
	: Y-coordinate	y(9)=476 mm
Point 10	: X-coordinate	x(10)=175 mm
	: Y-coordinate	y(10)=476 mm
Point 11	: X-coordinate	x(11)=175 mm
	: Y-coordinate	y(11)=32 mm
Point 12	: X-coordinate	x(12)=0 mm
	: Y-coordinate	y(12)=32 mm
Point 13	: X-coordinate	x(13)=0 mm
	: Y-coordinate	y(13)=0 mm

Sectional properties

Cross-sectional area	27616 mm ²
Second moments of area (inertias)	Ixx=0.96626E9 mm ⁴ Iyy=80.844E6 mm ⁴
Product of inertia $\int dA xy$	Ixy=0.10134E9 mm ⁴
Distance of centroid from origin	X=173.21 mm Y=222.29 mm
Principal second moments of area	Iu=0.97771E9 mm ⁴ Iv=69.392E6 mm ⁴

Check :- *JLR* 1/7/04
(Input only)

Page: 2
Made by: JCW
Date: 16.05 04
Ref No:

Office: 6114

Angle of principal U
counter-clockwise from XX-axis -6 4469 degrees

No650

under nail

Office: 6114

Section properties of a ~~plate girder with welded connections~~

Location Int beam

Number of bottom flange plates	nobfp=1
Number of top flange plates	notfp=1
Bottom flange plate	
Breadth	bbf(1)=381 mm
Depth	dbf(1)=32 mm
Web plate	
Breadth	bw=32 mm
Depth	dw=393.2 mm
Top flange plate	
Breadth	btf(1)=152 mm
Depth	dtf(1)=32 mm
Section properties	
Bottom flange	
Bottom flange plate	
Breadth	b(1)=bbf(i)=381 mm
Depth	d(1)=dbf(i)=32 mm
Second moment of area	$I_x(1)=b(n)*d(n)^3/12=381*32^3/12$ =1 0404E6 mm ⁴
Second moment of area	$I_y(1)=d(n)*b(n)^3/12=32*381^3/12$ =0 14748E9 mm ⁴
Area	A(1)=b(n)*d(n)=381*32=12192 mm ²
Distance from top of plate to bottom of section	
Distance	Db(1)=d(n)=32 mm
Distance of centroid from bottom	Cb(1)=Db(n)-d(n)/2=32-32/2 =16 mm
Total depth of bottom flange	tdbf=Db(n)=32 mm
Total area of bottom flange	12192 mm ²
Web	
Breadth of section	b(2)=bw=32 mm
Depth of section	d(2)=dw=393.2 mm
Second moment of area	$I_x(2)=b(n)*d(n)^3/12=32*393.2^3/12$ =0.16211E9 mm ⁴
Second moment of area	$I_y(2)=d(n)*b(n)^3/12=393.2*32^3/12$ =1 0737E6 mm ⁴
Area	A(2)=b(n)*d(n)=32*393.2=12582 mm ²
Distance from top of web to bottom of section	
Distance	Db(2)=Db(p)+d(n)=32+393.2 =425.2 mm
Distance of centroid from bottom	Cb(2)=Db(n)-d(n)/2=425.2-393.2/2 =228.6 mm
Top flange	
Top flange plate	
Breadth	b(3)=btf(i)=152 mm
Depth	d(3)=dtf(i)=32 mm
Second moment of area	$I_x(3)=b(n)*d(n)^3/12=152*32^3/12$ =415061 mm ⁴

Check: *gJR* 1/7/04.
 (input values)

Office: 6114

Second moment of area $I_y(3) = d(n) * b(n)^3 / 12 = 32 * 152^3 / 12$
 $= 9.3648E6 \text{ mm}^4$
 Area $A(3) = b(n) * d(n) = 152 * 32 = 4864 \text{ mm}^2$
 Distance to top of plate from bottom of section
 Distance $Db(3) = Db(p) + d(n) = 425.2 + 32$
 $= 457.2 \text{ mm}$
 Distance to centroid from bottom $Cb(3) = Db(n) - d(n) / 2 = 457.2 - 32 / 2$
 $= 441.2 \text{ mm}$
 Total depth of top flange $tdtf = Db(n) - dw - tdbf = 457.2 - 393.2 - 32$
 $= 32 \text{ mm}$
 Total area of top flange 4864 mm^2

SECTION SUMMARY

Gross section elastic properties

Depth of girder $dob = Db(n) = 457.2 \text{ mm}$
 Area 29638 mm^2
 1st moment of area about soffit $5.2174E6 \text{ mm}^3$
 Centroid of section from soffit $CGga = Mga / Ga = 5.2174E6 / 29638$
 $= 176.04 \text{ mm}$
 Second moments of area about centroidal axes
 About x-x axis $0.85258E9 \text{ mm}^4$
 About y-y axis $0.15792E9 \text{ mm}^4$
 Elastic section moduli
 Top $Ztg = I_{gxx} / (dob - CGga)$
 $= 0.85258E9 / (457.2 - 176.04)$
 $= 3.0323E6 \text{ mm}^3$
 Bottom $Zbg = I_{gxx} / CGga = 0.85258E9 / 176.04$
 $= 4.8432E6 \text{ mm}^3$

Gross section plastic properties

Half gross area $hga = Ga / 2 = 29638 / 2 = 14819 \text{ mm}^2$
 Equal area line is in web
 Distance from beam soffit $eal = Db(m) - (ca - hga) / b(m)$
 $= 425.2 - (24774 - 14819) / 32$
 $= 114.1 \text{ mm}$
 Plastic modulus $4.4434E6 \text{ mm}^3$

No652

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

BRIDGE NAME Auchmacoy
RAILTRACK NO EBD 761

Assessment should include completion of all three Sections even where Section 1 has shown the bridge deck to be non-compliant

SECTION 1 CHECKS FOR COMPLIANCE WITH 24 T CONFIGURATION REQUIREMENTS

		Compliant Yes/No
What is maximum clear span of the arch <i>Non-compliant if greater than 2.0m</i>	1.25m 0.875m ✓	Yes
Do jack arches spring from bottom flanges of beams? <i>If not, non compliant</i>	Yes	Yes
What is the beam spacing? What is the rise of the arch? Gross aspect ratio <i>Non-compliant if greater than 10</i>	$b = \frac{1.256}{0.212} = 5.92$ $r_c = 0.229m$ $\frac{b}{r_c} = 5.459$	Yes
What is the arch barrel thickness (including concrete fill above) and how is it derived ie from record drawings or site investigation? <i>Non-compliant if thickness less than 220</i>	$d = 177mm$ ✓	No !

Check - JLR
1/7/04


PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

BRIDGE NAME. Auchmacoy
RAILTRACK NO EBD 761

Assessment should include completion of all three Sections even where Section 1 has shown the bridge deck to be non-compliant

SECTION 2 CHECKS FOR DEFICIENCY

Type No	Deficiency	Pass/Fail
2	<p>What is the backing material? Is it structural? Concrete, soil and stones Yes</p> <p>Does the structural backing extend to at least the crown level of the arch extrados? If not, then fail (1) (4) Yes</p> <p>Height of structural fill above crown $d_f = 25\text{mm}$</p> <p>What is effective shear depth of deck? (= arch rise + barrel thickness + depth of structural fill above crown of extrados)</p> <p>$D_s = r_c + d + d_f$ $D_s = 431\text{ mm}$</p> <p>$212 + 152 + 25 = 389\text{ mm} > 320\text{ mm}$</p> <p>Is $D_s \geq$ "minimum requirements of Fig 1" Fail if $<$ Fig 1 <u>OK</u></p> <div style="text-align: center;">  <p>Figure 1</p> </div>	<p>Pass</p> <p>Pass ✓</p>
	<p>Do jack arches span longitudinally (eg in half through girder construction) or transversely between longitudinal girders? Transversely</p> <p>For longitudinal spanning jack arches, ignore following questions on ties/lateral restraint and state N/A</p> <p>Are ties provided in edge bays of transversely spanning jack arches?</p>	<p>Fail</p>

Check:- JFR 1/7/04. The existing ties are not efficient any more

	<i>If yes, go to 3a/3b</i>	<i>If not, fail unless edge bay is 'hard' (see 5)</i>	
3a	What is the cross sectional area of one tie? (allowing for corrosion losses)	Diameter of tie Dia = 32mm	
CI	Therefore Area $A = \pi \frac{(\text{Dia})^2}{4}$	$A = 804\,248\text{ mm}^2$	
	What is number of ties per beam length?	$n = 2$	
	What is the clear skew span?	$L = 5\text{m}$	
	Specific area of tie $A_s = \frac{(n+1) A}{L}$	$A_s = 482\,549 \frac{\text{mm}^2}{\text{m}}$	Fail
		<i>Non-compliant if less than 260mm²/m</i>	
	What is maximum tie spacing?	$S = 1.5\text{m}$	Fail
		<i>Non-compliant if greater than 2.5m for cast iron</i>	
3b	What is the cross sectional area of one tie? (allowing for corrosion losses)	Diameter of tie Dia = 35mm	
WI/ST	Therefore Area $A = \pi \frac{(\text{Dia})^2}{4}$	$A = 962\,113\text{ mm}^2$	
	What is number of ties per beam length?	$n = 2$	
	What is the clear skew span?	$L = 5\text{m}$	
	Specific area of tie $A_s = \frac{(n+1) A}{L}$	$A_s = 577\,268 \frac{\text{mm}^2}{\text{m}}$	
		<i>Non-compliant if less than 260mm²/m</i>	
	What is maximum tie spacing?	$S = 2\text{m}$	
		<i>Non-compliant if greater than 3.0m for wrought iron/steel</i>	Pass
4	Are ties located within crown of external arch?	No	
		<i>If so, then fail CI or possible fail for WI/steel</i>	
5	Does external bay construction provide alternative lateral restraint? (ie not soft edge)?		
	<i>If so, pass</i> <i>If not, are ties provided in first Jack Arch bay? if yes, treat as 3a (or 3b) otherwise fail</i>		Pass

Notes (1) Results also in loss of D/d (composite action) for cast iron beams

(4) A trial hole should be undertaken to confirm the existence of structural backing if there is any doubt

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

BRIDGE NAME	<i>Auchmarney</i>
RAILTRACK NO.	<i>= BD 761</i>

check, gJR 1/7/04

Assessment should include completion of all three Sections even where Section 1 has shown the bridge deck to be non-compliant

SECTION 3 CHECKS FOR DEFICIENCY

Type No	Defect	Empirical Assessment		Pass/Fail
		CI Decks	W/Steel Decks	
6	Rotation of supporting beam <i>No rotation</i>	Fail	Fail	Pass
7	Horizontal displacement of supporting beam <i>None</i>	Fail	Fail	Pass
8	Inadequate support to springings eg corrosion of bottom flange of supporting beam over a significant length, missing bedding mortar <i>OK</i>	Possible Fail	Possible Fail	Pass
9	Transversely bowed bottom flange of supporting beam <i>No</i>	Fail	Fail	Pass
10	Cracking at crown of arch owing to spreading of springings (other than 12, 13) <i>None</i>	Fail	Fail	Pass
11	Distortion and any associated cracking of jack arch barrel <i>None</i>	Fail	Fail	Pass
12	Arch crack resulting in substructure crack <i>None</i>	Fail	Fail (5)	Pass
13	Substructure crack or other distress resulting in crack to jack arch <i>None</i>	Possible Fail (3)	Possible Fail (3) (5)	Pass

Notes (3) 'Substructure renovation' or 'Monitoring' as appropriate, 'Repair of arch' (if appropriate)
(5) Not applicable in general to longitudinally spanning arches

Check: *JLR 1/7/04*