

British Rail Property Board, 2001/02

Bedfordshire County Council

Southill Road Railway Bridge

No. HIB27

Assessment Report

Our ref
Please reply to
Direct Dialling No
E-mail Address

BP/80714

Your ref



Bedfordshire
county council

9th July 2003

Mr [REDACTED]
British Railways Board (Residuary) Ltd
Rail Property Ltd
Hudson House
YORK
Y01 6HP



c/o Babbie Group
PO Box 272
The Merton Centre
45 St. Peter's Street
Bedford MK40 2ZY

Tel : 01234 763400
Fax: 01234 763401

Dear [REDACTED]

ASSESSMENT OF BRB BRIDGES IN BEDFORDSHIRE
SOUTHILL ROAD RAILWAY BRIDGE (HIB27)
AMENDED ASSESSMENT

We have now completed our re-assessment of HIB27 as discussed at our meeting of 25th June 2003.


As expected, the use of the revised joint depth factor has increased the allowable single axle load to 9.0 tonnes. The assessed capacity of the bridge is now 13 Tonnes (12.5T GVW).

As previously agreed at our meeting I enclose the following revised pages for incorporation into your copy of the previous report.

- Page Nos 1, 2, 4, 6 & 7 of the assessment report
- Amended Form BA (2 pages)
- Amended Form BAA (2 pages)
- Amended calculation pages 5, 6, 6a, 10 & 15.

I look forward to receiving a copy of the countersigned Forms BA and BAA in due course.

Yours sincerely



DOCUMENT ISSUE RECORD

[illegible]

Copyright Babbie Group Limited. All rights reserved.

No part of this report may be copied or reproduced by any means without prior written permission from Babtie Group Limited. If you have received this report in error, please destroy all copies in your possession or control and notify Babtie Group Limited.

This report has been prepared for the exclusive use of the commissioning party and unless otherwise agreed in writing by Babbie Group Limited, no other party may use, make use of or rely on the contents of the report. If others choose to rely upon this report they do so entirely at their own risk. No liability is accepted by Babbie Group Limited for any use of this report, other than for the purposes for which it was originally prepared and provided.

Opinions and information provided in the report are on the basis of Babtie Group Limited using due skill, care and diligence in the preparation of the same and no explicit warranty is provided as to their accuracy. It should be noted and it is expressly stated that no independent verification of any of the documents or information supplied to Babtie Group Limited has been made.

Contents

<u>SECTION</u>	<u>TITLE</u>	<u>Page</u>
	Document Issue Record	1
	Synopsis of Assessment Results	2
	Contents	3
1.0	Introduction	4
2.0	Assessment	4
2.1	Assessment of Brick Arch	4
2.2	Assessment of Substructure and Foundations	4
3.0	Design Parameters and Material Strengths Used in the Assessment	4
3.1	Factors used for Modified MEXE Method	4
3.2	Arch Profile	4
3.3	Additional Information	5
3.4	Assessment Loading	5
4.0	Assessment Results	6
4.1	Structure Assessment Summary of Results	6
4.2	Substructure & Foundations	7
5.0	Discussion of Assessment Results	7
6.0	Conclusions	7

APPENDICES

APPENDIX A	Approval in Principle
APPENDIX B	Assessment and Check Certificate
APPENDIX C	Assessment Calculations
APPENDIX D	Assessment Inspection Report

SYNOPSIS OF ASSESSMENT RESULTS

Arch Assessment

**The Assessment Capacity of the Bridge is 12.5 Tonnes
GVW (13 Tonne Restricted Live Loading) with no
restriction to Fire Engine Group 2.**

1.0 Introduction

1.1 Structure Details

Bridge name	Southill Road Bridge
Bridge no.	Rail: HIB 27 BCC U147/9027
OS reference	TL 0907 4689

1.2 Structure Description

The bridge carries the U147 Southill Road over a disused railway and is located 1 km south of Cardington village. The date of construction is not known, but possibly built in 1855 as other bridges on the same line.

The bridge is a single span four ring brick arch supported on brick abutments. The wingwalls, spandrels and parapets are of brick. The foundations are assumed to be spread footings. The Bridge has a skew of 21 degree.

2.0 Assessment

2.1 Assessment of Brick Arches

The assessment of the arch has been carried out using the Modified MEXE Method, and the capacity has been confirmed, using the ARCHIE computer program.

The assessment is based upon the AA form dated 28th April 2002, prepared by the Babbie Group on behalf of Bedfordshire County Council. Centrifugal effects have been ignored in the assessment as the road is of straight alignment over the structure. Axle-lift off has been considered in the assessment because of the humped vertical curve over the structure.

2.2 Assessment of Substructure and Foundations

The abutments and wing walls have been assessed qualitatively in accordance with Chapter 8 of BD 21/01.

3.0 Design Parameters and Material Strengths used in the Assessment

The following parameters and material strengths (as stated in the Principle Inspection report, Appendix F) have been used in the assessment.

3.1 Factors used for modified MEXE method and ARCHIE collapse mechanism method

The following factors have been determined from the assessment inspection and used in the MEXE and ARCHIE assessments of each arch:

Barrel Factor F_b	1.0	
Fill Factor F_f	0.7	
Joint Width Factor F_w	0.9	
Mortar Factor F_{mo}	1.0	
Joint Depth Factor F_d	0.9	(As bottom ring ignored, F_d taken as 1.0)
Condition Factor F_{cm}	0.6	

No record drawings are available for the structure, which state type of brickwork and mortar used.

3.2 Arch Profile

The inspection has identified that there is longitudinal cracking, seepage deposit and areas of hollow sounding brickwork in the arch intrados. Therefore a barrel with thickness of 3 rings has been used in the assessment as it is assumed the lower (fourth) ring is ineffective due to ring separation.

3.3 Additional information

Additional information was obtained from the following drawings, which are contained in Appendix B and D of the Assessment Inspection Report.

Drg. Nos.	Drawing Description
HIB27/1	Plan And Levels
HIB27/2	East Elevation
HIB27/3	West Elevation
HIB27/4	Cross Sections 1
HIB27/5	General Arrangement
HIB27/06	Elevations Defects
HIB27/07	Arch Defects
HIB27/08	Abutment Defects
HIB27/09	Carriageway Defects

3.4 Assessment Loading

The structure has been assessed for the 40/44 tonne assessment live loading in accordance with the Approval in Principle document.

4.0 Assessment Results

4.1 Structure Assessment Summary of Results:

<u>Structure Name:</u> SOUTHILL ROAD BRIDGE	HIB 27 BCC U147/9027	
MODIFIED MEXE ANALYSIS		
ASSESSMENT LIVE LOADING		
Allowable gross Axle Weight:	Axle weight	Capacity
Single axle	9.03 T	12.5 T GVW
Double axle bogie (lift off)	4.37 T	-
Triple axle bogie	5.25 T	-
CAPACITY	12.5 Tonnes GVW (13 Tonne Restriction) with no Restriction to Fire Engine Group 2 (From ANNEX F, Table F1 – BD21/01)	

<u>Structure Name:</u> SOUTHILL ROAD BRIDGE	HIB 27 BCC U147/9027
ARCHIE ANALYSIS	
ASSESSMENT LIVE LOADING	PASS/FAIL
Single Axle 10.5t (33-17t Restriction)	Fail
Double Axle 18t (25t Restriction)	Fail
Single Axle (13t Restriction)	Fail
Single Axle (10t Restriction)	Fail
Single Axle (7.5t Restriction)	Fail
Single Axle (3.0t Restriction)	Pass

The following boxes are NOT to be completed by the Consultant unless authorised to do so by the Employer's Representative.

SI 1705 (1972) Loading	
Pass / Fail	

4.2 Substructure and Foundations

The abutments and the walls were assessed visually during the assessment inspection in accordance with Chapter 8 of BD 21/01. There are a number of hairline cracks in both north and south abutment walls, which may appear to be due to movement/settlement of foundations. However it is considered that the condition factor of 0.6 has taken this into account in the assessment of the arch.


There are a number of defects such as areas of poor joints, surface spalling, hollow brickwork, bulging and cracks to both south-east and south-west wingwalls. Whilst there is no evidence of failure of the walls due to rotation or forward movement, the above mentioned defects do give cause of concern. The walls are accordingly considered to be inadequate by inspection until such time as the defects are repaired, and the walls proven adequate by calculation. As the thicknesses of the walls and dimensions of their foundations, and ground conditions are unknown, an extensive site investigation would need to be carried out prior to any proposed analytical assessment.

5.0 Discussion of Assessment Results

- 5.1 The assessment of the arch using the Modified MEXE Method indicates that it is capable of carrying vehicles of 12.5 T GVW (13 tonne restricted live loading) with no restrictions to Fire Engine Group 2.
- 5.2 A collapse mechanism analysis was carried out using the computer program ARCHIE in order to confirm the capacity of the arch. It gave a result of 3.0 tonnes. Therefore, in accordance with Clause 6.19 (i) in Chapter 6 of BD21/01, the capacity of 12.5 tonnes GVW calculated by the Modified MEXE Method shall be taken.
- 5.3 Ignoring the bottom ring in the assessment may be considered overly conservative. A sensitivity analysis was carried out in order to determine whether using 4 ring thick arch barrel and reducing the condition factor from 0.6 to 0.4 would significantly affect the results. The Capacity of the structure using modified MEXE method appears to lie between 10 and 18 tonnes depending upon the condition factor and number of rings used.
- 5.4 Investigation to determine the extent of ring separation is likely to prove inconclusive and is therefore not considered to be cost effective. Strictly in accordance with AIP, the capacity of the structure is 12.5 tonnes.


6.0 Conclusions

- 6.1 The overall carrying capacity of the structure is 12.5 tonnes GVW (13T Live Load Restriction) with no restrictions to Fire Engine Group 2.

Signed:  ...

Date:

Name:

Signed: 

Date:

Name:

APPENDIX A

Approval in Principle

FORM 'AA' (BRIDGES)**GC/TP0356**

ELR/ Bridge No HIB 27

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT

Bridge/Line Name Southill Road Railway Bridge
ELR/Bridge No. HIB 27

Brief Description of Existing Bridge:**(a) Span Arrangement**

Single span masonry arch with skew span of 8.575 metres

(b) Superstructure Type

Square spanning single span brickwork arch. Voussoirs indicate a 4 ring arch 2 bricks thick.

(c) Substructure Type

Brickwork abutment, spandrels and wing walls.

(d) Details of any Special Features

None

Assessment Criteria**(a) Loadings and Speed**

40/44 Tonne assessment loading of BD21/01.

There is no specific speed restriction on the road over the bridge.
Therefore the general speed limit of 60mph (97 kph) for single carriageway roads applies.

(b) Codes to be used

RT/CE/P/010 (Issue 2-Dec 1997) Technical Approval Procedures for
Assessment of Bridges and Other Structures.

BD21/01 The Assessment of Highways Bridges and Structures

BA16/97 The Assessment of Highways Bridges and Structures
(Advice Note)

BA55/00 The Assessment of Bridge Substructures and Foundations,
Retaining Walls and Buried Structures (Advice Note)

FORM 'AA' (BRIDGES)

GC/TP0356

ELR/ Bridge No HIB 27

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT

(c) Proposed Method of Structural Analysis

The structure will be assessed initially using the Modified MEXE method. The inspection indicated large areas of hollow sounding brickwork. Accordingly it is proposed that the arch is assessed as consisting of 3 rings rather than 4. If the depth of fill over the arch exceeds the arch ring thickness then the depth of fill will be restricted to this lesser value in the calculations. If the capacity of the arch is below the 40/44 Tonne assessment level then the arch capacity will be confirmed using the ARCHIE computer program.(see Cl. 6.17 of BD21/01). Abutments and wingwalls will be assessed qualitatively in accordance with BD21/01 and BA55/00.

(d) Details of any Special Requirements

None

Senior Civil Engineer's Comments

None

Proposed Category for Independent Check 1

Superstructure 1

Substructure 1

Name Of Checker Suggested If Cat 2 Or 3

Category 1

The above assessment, with amendments shown, is approved in principle:

Signed ..

Title ..

Date ..



FORM 'AA' (BRIDGES)**GC/TP0356**

ELR/ Bridge No HIB 27

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT**Category 2 and 3**

The above assessment, with amendments shown, is approved in principle:

Signed

Title

Date

Signed

Title

Date

FORM 'AA/1' (BRIDGES)**GC/TP0356**

Appendix: 4

Issue: 1

ELR/ Bridge No HIB 27

Revision: B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT**Additional Information Required For BRB (Residuary) Limited Owned
Public Road Overbridges Assessed As Part Of Bridgeguard III**

Bridge/Line Name Southill Road Railway Bridge

ELR/Bridge No. HIB 27

Scope Of Assessment Assessment of ability of the structure to carry current
highway loading**Assessment Criteria****(a) Standards And Codes Of Practice To Be Used In Assessment**RT/CE/P/010 (Issue 2-Dec 1997) Technical Approval Procedures for
Assessment of Bridges and Other Structures.

BD21/01 The Assessment of Highways Bridges and Structures

BA16/97 The Assessment of Highways Bridges and Structures (Advice
Note)BA55/00 The Assessment of Bridge Substructures and Foundations,
Retaining Walls and Buried Structures (Advice Note)**(b) Proposed Method Of Structural Analysis**

The structure will be assessed initially using the Modified MEXE method. The inspection indicated large areas of hollow sounding brickwork. Accordingly it is proposed that the arch is assessed as consisting of 3 rings rather than 4. If the depth of fill over the arch exceeds the arch ring thickness then the depth of fill will be restricted to this lesser value in the calculations. If the capacity of the arch is below the 40/44 Tonne assessment level then the arch capacity will be confirmed using the ARCHIE computer program.(see Cl. 6.17 of BD21/01). Abutments and wingwalls will be assessed qualitatively in accordance with BD21/01 and BA55/00.

(c) Planned Highway Works/Modifications At This Site

None

(d) Road Designation Class And Whether Classed As A Heavy Load Route

Unclassified county road. Not a Heavy Load Route.

FORM 'AA/1' (BRIDGES)

GC/TP0356

ELR/ Bridge No HIB 27

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

APPROVAL IN PRINCIPLE FOR ASSESSMENT

(e) Any Other Requirements

None


The Above Is Agreed Subject To The Amendments And Comments Shown Below.

Signed

Title

For And On B

Date



Drawing Number

HIB27/05

Notes

Do not scale this drawing


Rev	Date	Checked

b Babbie


Client	BEDFORDSHIRE COUNTY COUNCIL
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON GENERAL ARRANGEMENT

Drawing No.	HIB27/05	Date	APRIL 2002
Scale	AS SHOWN	Drawn	SR
		Checked	PDS
		Approved	<i>[Signature]</i>



Copyright reserved
Babbie Group Ltd
Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY



EAST ELEVATION
1:100



SECTION A-A
1:100



PLAN
1:200

APPENDIX B

Assessment and Check Certificate

FORM 'BA' (BRIDGES)**GC/TP0356**

Appendix: 4

ELR/ Bridge No HIB/27

Issue: 1

Revision: A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECK

Assessment Group: Babbie Group, on behalf of Bedfordshire County Council

Bridge/Line Name: Southill Road Railway Bridge

Category Of Check: Category 1

ELR/ Bridge No HIB27


I certify that reasonable professional skill and care have been used in the assessment of the above structure with a view to securing that:

- (1) It has been assessed in accordance with the Approval in Principle (where appropriate) as recorded on Form AA approved on 3rd May 2002.
- (2) It has been checked for compliance with the following principal British Standards, Codes of Practice, BRB (Residuary) Limited Technical notes and Assessment standards.

List any departures from the above, and additional methods or criteria adopted, with reference and justification for their acceptance (commenting on the results if appropriate).

.....

.....

Category 1NameSignatureDate

ctor

FORM 'BA' (BRIDGES)**GC/TP0356**

Appendix: 4

ELR/ Bridge No HIB/27

Issue: 1

Revision: A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECKCategory 2 and 3 (Note: Category 1 Check Must Also Be Signed)(a) AssessmentNameSignatureDate

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible(b) CheckNameSignatureDate

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible

This Certificate Is Accepted By.....

20/8/2003

FORM 'BAA' (BRIDGES)**GC/TP0356**

Appendix: 4

ELR/ Bridge No HIB/27

Issue: 1

Revision: A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECKNotification of Assessment Check

Assessment Group: Babtie Group, on behalf of Bedfordshire County Council

Bridge/Line Name: Southill Road Railway Bridge

Category Of Check: Category 1

ELR/ Bridge No HIB27

The above bridge has been assessed and checked in accordance with Standards which are listed on the appended Form BA. A summary of the results of the assessment in terms of capacity and restrictions is as follows:-

STATEMENT OF CAPACITY

- a) 13 Tonnes with no restriction to Fire Engine Group 2.
- b) Fails under dead loads (by inspection).

Critical member/s:

- a) Arch Barrel.
- b) South-east & South-west wingwalls.

Recommended Loading Restrictions

Temporary measures to be put in place in accordance with BA 79/98

Description of Structural Deficiencies and Recommended Strengthening

<u>Name</u>	<u>Signature</u>	<u>Date</u>	
		6/03	Assessor
		/03	Assessment Checker
		7/03	Business Centre Director Babtie Group

FORM 'BAA' (BRIDGES)**GC/TP0356**

Appendix: 4

ELR/ Bridge No HIB/27

Issue: 1

Revision: A (Feb 1993)

CERTIFICATION FOR ASSESSMENT CHECKCategory 2 and 3 (Note: Category 1 Check Must Also Be Signed)(c) AssessmentNameSignatureDate

Assessor

Assessment Checker


Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible(d) CheckNameSignatureDate

Assessor

Assessment Checker

Partner Of the Firm Of
Consulting Engineers
To Whom Assessor/
Checker Is Responsible

This Certificate Is Accepted By..



20/8/2003.....

APPENDIX C

Assessment Calculations

Client: **Bedfordshire County Council**

Commission Title: **British Rail Property Board 2001/2**

Bridge Title: **Southill Road Railway Bridge,
Cardington, No. HIB27**

File Title: **Assessment Calculations**

File Ref: **080714**

BABTIE**CALCULATION SHEET**

OFFICE	BEDFORD	PAGE No.	INDEX	CONT'N PAGE No.	
JOB No. & TITLE	080714 - SOUTHILL RAILWAY BR	ORIGINATOR	MY	DATE	OCT '02
SECTION	ASSESSMENT CALC'S	CHECKER	AET	DATE	17/10/02

CALCULATION INDEX

	Page
Assessment Summary	Summary
Survey Data	1 - 2
MEXE Assessment	3 - 6
ARCHIE Assessment	7 - 10
ARCHIE Printouts	11 - 13
Arch Parameters	14
Sensitivity Analysis	15 - 19

BABTIE**CALCULATION SHEET**

OFFICE <i>BEDFORD</i>	PAGE No.	<i>Summary</i>	CONT'N PAGE No.
JOB No. & TITLE <i>080714 - SOUTHILL RAILWAY BR</i>	ORIGINATOR	<i>my</i>	DATE <i>OCT '02</i>
SECTION <i>ASSESSMENT CALC'S</i>	CHECKER	<i>AEH</i>	DATE <i>17/10/02</i>

ASSESSMENT SUMMARY

MEXE - 10 TONNES
ARCHIE - 3.0 TONNES.

*THE ASSESSMENT CAPACITY OF THE
BRIDGE IS 10 TONNES.*

OFFICE	BEDFORD	PAGE No.	1	CONT'N PAGE No.	
JOB No. & TITLE	080714 - Southill Railway BR - CARDINGTON	ORIGINATOR	MY	DATE	28.08.07
SECTION	MEXE ASSESSMENT	CHECKER	DET	DATE	17/10/12

ASSESSMENT OF MASONRY ARCH BRIDGE BY MODIFIED MEXE METHOD

3 ring thick arch barrel is used in the assessment (AIP)

- Span (L) : = East Elevation = 8.794 m
West Elevation = 8.739 m

$$\therefore L = \frac{8.794 + 8.739}{2} = 8.767 \text{ m}$$

$$L = 8.767 \text{ (m)}$$

(All dimensions measured off survey drawing using Autocad - drg No. H1827/02 & H1827/03 see Pages 283)

- Rise of the arch barrel at the crown (r_c):

$$\begin{aligned} \text{East Elevation} &= 1.993 \text{ m} \\ \text{West Elevation} &= 1.989 \text{ m} \end{aligned} \quad \therefore r_c = \frac{1.993 + 1.989}{2} = 1.991 \text{ m}$$

$$r_c = 1.991 \text{ (m)}$$

- The Rise of the arch barrel at the quarter points (r_q):

West Elev	East Elev	
1.580	1.568	$\therefore r_q = \frac{1.580 + 1.573 + 1.568 + 1.572}{4}$
1.573	1.572	


$$r_q = 1.573$$

$$r_q = 1.573 \text{ (m)}$$

- Thickness of the arch barrel adjacent to the Key Stone (3 Ring) "d" = 0.360 m


$$d = 0.360 \text{ (m)}$$

SURVEY DATA SHEET 1



Southill Railway Bridge - Cardington

SURVEY DATA SHEET (2)



Calcs Page 3

3 RINGS ARCH BARREL

Checked
RET 17/10/02

BABTIE
CALCULATION SHEET

OFFICE <i>21/10/02</i>	PAGE No. <i>4</i>	CONT'N PAGE No.	
JOB No. & TITLE <i>080710 - SOUTHILL RAILWAY BR - CARLINGTON</i>	ORIGINATOR <i>MY</i>	DATE <i>27/02/02</i>	
SECTION <i>MEXE ASSESSMENT</i>	CHECKER <i>QEN</i>	DATE <i>17/10/02</i>	

Average depth of full (h) =

$$d+h = \frac{0.673 + 0.708}{2} = 0.691 - 0.120 = 0.571 \text{ m}$$

(d+h measured off Drg H1827/02 & H1827/03) (with ring)

$$\therefore h = (d+h) - d \Rightarrow 0.691 - (0.360 + 0.120)$$

$$h = 0.211 \text{ m}$$

$$h = 0.211 \text{ (m)}$$

Provisional axle loading (PAL)

$$PAL = \frac{740 (d+h)^2}{L^{1.3}}$$

$$PAL = \frac{740 (0.360 + 0.211)^2}{8.767^{1.3}}$$

$$PAL = 14.348 \text{ TONNES}$$

$$PAL = 14.348 \text{ TONNES}$$

MODIFYING FACTORS

Span/Rise Factor (F_{sr}):

$$F_{sr} = L/r_c \Rightarrow 8.767/1.991 = 4.403$$

As $4.403 > 4.000$, the F_{sr} from Fig 3/3 = 0.94

$$F_{sr} = 0.94$$

Profile Factor (F_p)

$$F_p = r_g/r_c \Rightarrow 1.573/1.991 = 0.79$$

$$0.79 > 0.75 \therefore F_p = 2.3 \left[\frac{r_c - r_g}{r_c} \right]^{0.6} \Rightarrow 2.3 \left[\frac{1.991 - 1.573}{1.991} \right]^{0.6}$$

$$F_p = 0.90$$

$$F_m = 0.90$$

$$F_{cm} = 0.6$$

BABTIE		CALCULATION SHEET		
OFFICE	BEDFORD	PAGE No.	5	CONT'N PAGE No.
JOB No. & TITLE	08/0714 - SOUTHILL RAILWAY BR - CARDINGTON	ORIGINATOR	MY	DATE 28.08.02
SECTION	MESE ASSESSMENT	CHECKER	QET	DATE 17/10/02

Condition Factors (from Assessment Inspection Report)

$$F_b = 1.0$$

$$F_f = 0.7$$

$$F_w = 0.9$$

$$F_{mo} = 1.0$$

$$F_d = 0.9$$

$$F_{cm} = 0.6 \text{ (Due to longitudinal cracking)}$$

1.0 (if bottom ring ignored)

Material Factor (F_m):

$$F_m = \frac{(F_b \times d) + (F_f \times h)}{d + h}$$

$$F_m = \frac{(1.0 \times 0.360) + (0.7 \times 0.211)}{0.360 + 0.211}$$

$$F_m = 0.89$$

Joint Factor (F_j)

$$F_j = F_w \times F_d \times F_{mo}$$

$$F_j = 0.9 \times \frac{0.9}{1.0} \times 1.0 \Rightarrow 0.81$$

Modified axle load = $F_{sr} \times F_p \times F_m \times F_j \times F_{cm} \times PAL$

$$= 0.94 \times 0.90 \times 0.89 \times \frac{0.9}{1.0} \times 0.6 \times 14.348$$

$$= 5.250 \text{ (T)}$$

$$= 5.83 \text{ T}$$

Axle life off assumed due to hump backed road alignment.

QET 25/6/03

$F_m = 0.89$

$F_j = 0.81$
QET 25/6/03

QET
25/6/03

BABTIE

CALCULATION SHEET

OFFICE	BEDFORD	PAGE No.	6	CONT'N PAGE No.	6a
JOB No. & TITLE	080714 - SOUTHILL RAILWAY BR - CARDINGTON	ORIGINATOR	MY	DATE	28.08.02
SECTION	MEXE ASSESSMENT	CHECKER	QEF	DATE	17/10/02

Allowable axle loads : (Lift-off)

$$\begin{array}{lcl}
 \text{Single Axle} : & \frac{5.83}{5.250} & \times 1.55 \text{ (Fig 3/5a)} = \frac{9.03}{8.138} \text{ (T)} \\
 \text{2 Axle bogie} : & \frac{5.83}{5.250} & \times 0.75 \text{ (Fig 3/5b)} = \frac{4.37}{3.938} \text{ (T)} \\
 \text{3 Axle bogie} : & \frac{5.83}{5.250} & \times 0.90 \text{ (Fig 3/5a)} = \frac{5.25}{4.725} \text{ (T)}
 \end{array}
 \left. \begin{array}{l} \\ \\ \end{array} \right\} \begin{array}{l} \text{QEF} \\ 25/6/03 \end{array}$$

$$\underline{\text{MAX GROSS VEHICLE WEIGHT}} = \frac{12.5}{10} \text{ TONNES}$$

(ANNEX F, Table F1)
BD 21/01

QEF
25/6/03

MEXE ASSESSMENT

Check Spreadsheet

pg 6a
Q&A 25/6/03.

Project: **80714**
Structure: **Southill Road Railway Bridge HIB27 (With bottom ring ignored due to ring separation)**

Sheet No. 1

MEXE Analysis to BA 16/97 (With axle lift-off)

$$L = 8.767 \quad r_c = 1.991 \quad r_q = 1.573 \quad d = 0.36 \quad h+d = 0.571$$

Adjustment to limit $h+d$ to $2*d$ not required 1

$$F_b = 1 \quad F_f = 0.7 \quad F_w = 0.9 \quad F_{mo} = 1 \quad F_d = 1 \quad F_{CM} = 0.6$$

*Taken as 1.0
as bottom ring being ignored.*

Clause No:

- 3.10) Provisional Axle Load = $740(d+h)^2/L^{1.3} = 14.35$ tonnes
- 3.11) Span/Rise Factor $L/r_c = 4.40$ Hence $F_{sr} = 0.94$ (Fig 3/3)
- 3.12) Profile Factor $F_p = 2.3((r_c - r_q)/r_c)^{0.6} = 0.90$
- 3.13) Material Factor $F_m = ((F_b * d) + (F_f * h)) / (d+h) = 0.89$
- 3.16) Joint Factor $F_j = F_w * F_d * F_{mo} = 0.90$
- 3.24) Modified Axle Load = $F_{sr} * F_p * F_m * F_j * F_{CM} * PAL = 5.83$ tonnes
- 3.27) With axle lift - off : Fig's 3/5a and 3/5b Af for 2 axle bogie = 0.75
- a) Single Axle $A_r = 1.55$ Allowable Axle = 9.0 tonnes
- b) 2 Axle bogie $A_r = 0.75$ Allowable Axle = 4.0 tonnes


From Table 3/6 Max Gross Vehicle Weight = 12.5 tonnes

BABTIE
CALCULATION SHEET

OFFICE	BEDFORD	PAGE No.	7	CONT'N PAGE No.	
JOB No. & TITLE	080714 - SOUTHILL RAILWAY BRIDGE	ORIGINATOR	MY	DATE	02.09.02
SECTION	ARCHIE ASSESSMENT	CHECKER	RET	DATE	17/10/02

MEXE Results to be checked on ARCHIE

ARCH PROFILE




Dimensions in mm

Arch Co-ordinates

0	,	0
1096	,	1051
2192	,	1584
3288	,	1882
4384	,	1991
5479	,	1886
6575	,	1567
7671	,	989
8767	,	0

OFFICE	BEDFORD	PAGE No.	8	CONT'N PAGE No.	
JOB No. & TITLE	080714 - SOUTHILL RAILWAY BR - CARDINGTON	ORIGINATOR	MY	DATE	30.08.02
SECTION	ARCHIE ASSESSMENT	CHECKER		DATE	

- Span (L) : 8.767 m
- Rise (R) = 1.991 m
- Road profile - obtained from elevation drawings.



Dimensions in mm


- Ring thickness (3 rings) = 0.360 m
- Masonry Density = 21 kN/m³
- Fill Density = 20 kN/m³
- $\phi = 30^\circ$
- Material strength = 2.5 N/mm²
- Surfacing depth = 100 mm
- Surfacing density = 22 kN/m³
- Position of backfill unknown therefore not considered

$$d = 0.360 \text{ (m)}$$

(Reduction of Material strength not necessary as 4th ring is ignored in assessment)

OFFICE BEDFORD	PAGE No. 9	CONT'N PAGE No.	
JOB No. & TITLE 080714 - SOUTHILL RAILWAY BR - CARDINGTON	ORIGINATOR MY	DATE 02.09.02	
SECTION ARCHIE ASSESSMENT	CHECKER QET	DATE 17/10/02	

Effective Barrel width



$$\text{Wheel spread} = 300 + 211 \times \frac{3}{2} = \underline{511 \text{ mm.}}$$

$$\text{c/way width} = 4.650 \text{ (m)} - (\text{AIP})$$

Longitudinal crack approx in the centre of c/way,
 \therefore only one vehicle can be positioned on the bridge.

$$\text{Effective Barrel width} = 1.5 + h \Rightarrow 1.5 + 0.211$$

$$= \underline{1.711 \text{ m}}$$

$$\text{Eff Barrel } w/2 \text{ (NO of wheels)} = 1.711/2 \Rightarrow \underline{0.856 \text{ m}}$$

$$\text{Actual Axle load } w = 1.8 + 0.511 = 2.311 \text{ m}$$

$$\text{Effective Barrel width} = 2.311 + (0.856 - \frac{0.511}{2}) = \underline{2.912 \text{ m}}$$

\therefore use loadspread of 3.0 m

OFFICE	BEDFORD	PAGE No.	10	CONT'N PAGE No.	
JOB No. & TITLE	080714 - SOUTHILL ROAD RAILWAY BR	ORIGINATOR	MY	DATE	27.09.02
SECTION	ARCHIE ASSESSMENT	CHECKER	QST	DATE	17/10/02

Archie data files : S\BRIDGES\STRUCT\SHILL01.DAT

Archie printouts : COMMISSION FOLDER\Assessments\H1B27

Load spread of 3.0 m was used in Archie Assessment

Archie Results

	Req ring thickness (mm)	PASS / FAIL
1. Single Axle 10.5 (T) (33-17 t restrict)	537	FAILS
2. Double Axle 18 (T) (25 t Restriction)	577	FAILS
3. Single Axle 13 T Restriction	496	FAILS
4. Single Axle 10 T Restriction	432	FAILS
5. Single Axle 7.5 T Restriction	380	FAILS
6. Single Axle 3.0 T Restriction	230	PASSES

(see Archie printouts
attached as pages
AA05 - AA07)


ASSESSMENT RESULTS

MEXE - 12.5 TONNES
ARCHIE - 3.0 TONNES


∴ According to BD 21/97 (6.19(i)), modified
MEXE assessment shall stand.

CAPACITY OF STRUCTURE = 12.5 TONNES.


QST
25/6/03




FAILS




FAILS




FAILS



FAILS



FAILS



PASSES

Bedford
080714 BRPB Assessments
HIB27 Southill Road Railway Bridge
Arch Parameters

Page: 14
Originator: MY Sep'02
Checker: *act* 12/10/02

Southill			
Span	8767 mm	Rise	1991 mm
Depth of fill	220 mm	Depth of surfacing	100 mm
Ring depth	360 mm	Ring depth factor	1
Position of backing	0	Depth of mortar loss	0 mm
Fill density	20 kN/m ³	Masonry Density	21 kN/m ³
Surfacing density	22 kN/m ³		
Phi for fill	30 deg	Masonry strength	2.5 N/mm ²
Load	Single Axle 3t restriction) at 7000		
Lane width	3000mm		
Required ring depth	216 mm	Geometric F.O.S	1.67
H Left	82 kN/m	H Right	88 kN/m
V Left	117 kN/m	V Right	135 kN/m
Comp. zone at hinge	2 53 mm	Factor on pass. press.	.33
Hinges			
1 AT 2	2 AT 11	3 AT 16	4 AT 21

Param(mn).segment	Stone Weight	Vertical Dead Load	Horizontal Deadload	Vertical Live Load	Horizontal Live Load	Additional Pass Press
1	-3.8	-14.2	7.5	0	0	0
2	-3.9	-12.6	6.3	0	0	1.3
3	-3.9	-11.2	4.7	0	0	1.8
4	-3.9	-9.7	3	0	0	1.6
5	-3.9	-8	1.8	0	0	1.2
6	-3.8	-6.2	1.1	0	0	.8
7	-3.8	-4.9	.7	0	0	.6
8	-3.9	-3.8	.4	0	0	.4
9	-3.9	-3	.2	0	0	.2
10	-3.9	-2.6	.1	0	0	.1
11	-3.9	-2.5	0	0	0	0
12	-3.9	-2.9	-.2	0	0	0
13	-3.9	-3.6	-.4	0	0	0
14	-3.9	-4.7	-.7	-2.1	-.2	0
15	-3.9	-6.1	-1.2	-7.8	-1	0
16	-3.9	-7.8	-1.9	-8.7	-1.4	0
17	-3.9	-9.6	-3	-3.6	-.8	0
18	-3.9	-11.2	-4.5	-.2	-.1	0
19	-3.8	-12.7	-5.9	0	0	0
20	-3.8	-14.5	-7.1	0	0	0

BABTIE
CALCULATION SHEET

OFFICE	BEDFORD	PAGE No.	15	CONT'N PAGE No.	
JOB No. & TITLE	080714 - SOUTHILL RAILWAY BR	ORIGINATOR	MY	DATE	22/10/02
SECTION	SENSITIVITY ANALYSIS	CHECKER	QEN	DATE	17/10/02

Ignoring the bottom ring may be considered overly conservative, accordingly further assessment with 4 rings is carried out. Sensitivity Analysis to determine whether 4 ring thick arch barrel would increase Capacity.

$$L = 8.522 \text{ m}$$

$$F_b = 1.0$$

$$r_c = 1.951 \text{ m}$$

$$F_f = 0.7$$

$$r_g = 1.540 \text{ m}$$

$$F_w = 0.9$$

$$d = 0.480$$

$$F_{m0} = 1.0$$

$$h+d = 0.691$$

$$F_d = 0.9$$

$$F_{cm} = 0.6$$

For dimensions
see pages 18 & 19.

See attached spreadsheet on Page 16 following.

The overall Capacity increases to 18 TONNES. The overall condition factor of 0.6 is possibly too high. A reduced figure will be used to find the sensitivity of the structure to this parameter.

If Condition Factor is reduced to 0.4 (See Page 17)
= reduces to

The overall capacity ~~remains the same~~ 10 TONNES

26/6/03

See attached MEXE check spread sheets.

∴ The Capacity of the structure is governed by the assumed ring separation

The capacity of the structure appears to lie between 10 & 18 tonnes depending upon number of rings used and condition factor.

Strictly in accordance with the ATP. The capacity is ~~10~~ 12.5 TONNES.

QEN
26/6/03

Sensitivity Analysis

4 ring thick arch barrel - 480mm

Project: **80714**
 Structure: **Southill Road Railway Bridge HIB27**

Sheet No. 2

MEXE Analysis to BA 16/97 (With axle lift-off)

$L = 8.522$ $r_c = 1.951$ $r_q = 1.54$ $d = 0.48$ $h+d = 0.691$

Adjustment to limit $h+d$ to $2*d$ not required 1

$F_b = 1$ $F_f = 0.7$ $F_w = 0.9$ $F_{mo} = 1$ $F_d = 0.9$ $F_{CM} = 0.6$

Clause No:

3.10) Provisional Axle Load $= 740(d+h)^2/L^{1.3} = 21.80$ tonnes

3.11) Span/Rise Factor $L/r_c = 4.37$ Hence $F_{sr} = 0.94$ (Fig 3/3)

3.12) Profile Factor $F_p = 2.3((r_c - r_q)/r_c)^{0.6} = 0.90$

3.13) Material Factor $F_m = ((F_b * d) + (F_f * h)) / (d+h) = 0.91$

3.16) Joint Factor $F_j = F_w * F_d * F_{mo} = 0.81$

3.24) Modified Axle Load $= F_{sr} * F_p * F_m * F_j * F_{CM} * PAL = 8.21$ tonnes

3.27) With axle lift - off : Fig's 3/5a and 3/5b Af for 2 axle bogie $= 0.75$

a) Single Axle $A_r = 1.54$ Allowable Axle $= 12.5$ tonnes

b) 2 Axle bogie $A_r = 0.75$ Allowable Axle $= 6.0$ tonnes

From Table 3/6 Max Gross Vehicle Weight = 18 tonnes

Q27 17/10/02

Sensitivity Analysis

Condition Factor Reduced to 0.4

Project: 80714
Structure: Southill Road Railway Bridge HIB27

Sheet No. 2

MEXE Analysis to BA 16/97 (With axle lift-off)

$L = 8.522$ $r_c = 1.951$ $r_q = 1.54$ $d = 0.48$ $h+d = 0.691$

Adjustment to limit $h+d$ to $2*d$ not required 1

$F_b = 1$ $F_f = 0.7$ $F_w = 0.9$ $F_{mo} = 1$ $F_d = 0.9$ $F_{CM} = 0.4$

Clause No:

3.10) Provisional Axle Load = $740(d+h)^2/L^{1.3} = 21.80$ tonnes

3.11) Span/Rise Factor $L/r_c = 4.37$ Hence $F_{sr} = 0.94$ (Fig 3/3)

3.12) Profile Factor $F_p = 2.3((r_c - r_q)/r_c)^{0.6} = 0.90$

3.13) Material Factor $F_m = ((F_b * d) + (F_f * h)) / (d+h) = 0.91$

3.16) Joint Factor $F_j = F_w * F_d * F_{mo} = 0.81$

3.24) Modified Axle Load = $F_{sr} * F_p * F_m * F_j * F_{CM} * PAL = 5.47$ tonnes

3.27) With axle lift - off : Fig's 3/5a and 3/5b Af for 2 axle bogie = 0.75


a) Single Axle $A_f = 1.54$ Allowable Axle = 8.0 tonnes

b) 2 Axle bogie $A_f = 0.75$ Allowable Axle = 4.0 tonnes

From Table 3/6 Max Gross Vehicle Weight = 10 tonnes


Q27 17/10/02

Survey Data sheet ②



4 Rug Arch barrel

Survey Data sheet ①



APPENDIX D

Assessment Inspection Report

British Rail Property Board, 2001/02

Client: Bedfordshire County Council

Southill Road Railway Bridge

No. HIB27

**Draft
Assessment Inspection Report**

DOCUMENT ISSUE RECORD

[illegible]

Southill Road Railway Bridge No. HIB27

Contents

1.00	Introduction, Location Plans and General Arrangement	Page 2
2.00	Inspection and Inspection Report Form BE11/94	Page 6
3.00	Conclusions	Page 13
4.00	Recommendations	Page 14

Appendices

A	Photographs
B	Defects Drawings
C	Statutory Undertakers Apparatus Information
D	Dimension Check List and Survey Drawings
E	List of Record Drawings
F	Site Factors Affecting Assessment
G	AIP Form

Copyright Babbie Group Limited. All rights reserved.

No part of this report may be copied or reproduced by any means without prior written permission from the Babbie Group Limited. If you have received this report in error, please destroy all copies in your possession or control and notify Babbie Group Limited.

This report has been prepared for the exclusive use of the commissioning party and unless otherwise agreed in writing by Babbie Group Limited, no other party may use, make use of or rely on the contents of the report. If others choose to rely upon this report they do so entirely at their own risk. No liability is accepted by Babbie Group Limited for any use of this report, other than for the purposes for which it was originally prepared and provided.

Opinions and information provided in the report are on the basis of Babbie Group Limited using due skill, care and diligence in the preparation of the same and no explicit warranty is provided as to their accuracy. It should be noted and it is expressly stated that no independent verification of any of the documents or information supplied to Babbie Group Limited has been made.

Southill Road Railway Bridge No. HIB27

1.00 Introduction

1.01 Structure Details

Bridge no.	HIB27
OS reference	TL 0907 4689
Date of inspection	20/03/2002

1.02 Structure Description

1.02.1 The bridge carries the U147 Southill Road two-way single carriageway over a disused railway and is located 1 km south of Cardington village. The date of construction is not known but bridges on the same line were possibly built in 1855.

1.02.2 The bridge is a single span 4-ring brick arch springing from brick abutments. The wingwalls, spandrels and parapets are of brick.

1.02.3 There are no weight limit signs on the bridge.

1.03 Structure dimensions

Skew Span:	8.49m	Skew:	21°	Width between parapets:	6.03m
------------	-------	-------	-----	-------------------------	-------




East Elevation

Southill Road Railway Bridge No. HIB27


- 1.00 **Introduction cont.**
- 1.04 Inspection Details
 - 1.04.1 The structure was inspected as part of the British Rail Property Board Assessment programme.
 - 1.04.2 The structure was inspected in accordance with Department of Transport documents:
Standard BD 63/94 Inspection of Highway Structures.
Advice Note BA 63/94 Inspection of Highway Structures.
 - 1.04.3 The structure was inspected on the 20th March 2002.
 - 1.04.4 The inspection was undertaken during the day. The weather conditions were good/rain.
 - 1.04.5 The inspector was P Butler.
 - 1.04.6 The structure was inspected on foot and using an underbridge unit.
 - 1.04.7 No record drawings are available.
 - 1.04.8 The bridge was surveyed by the Bedford Babbie Group survey team and a plan, elevations and cross sections produced. Copies are enclosed in Appendix D.
- 1.05 Previous Inspection and Summary
 - 1.05.1 No previous inspection records were made available.

Southhill Road Railway Bridge No. HIB27



Location Plans




Scale 1:50000




Scale 1:2500



PLAN
1:200



EAST ELEVATION
1:100



SECTION A-A
1:100

Drawing Number

HIB27/05

Notes

Do not scale this drawing

Rev	Date	Checked

Babtie

Client	BEDFORDSHIRE COUNTY COUNCIL		
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES		
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON GENERAL ARRANGEMENT		

Drawing No.	HIB27/05	Date	APRIL 2002
Scale	AS SHOWN	Drawn	SR
		Checked	PDB
		Approved	

Copyright reserved
Babtie Group Ltd
Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY

Structure Inspection Report

BE 11/94

Structure Number	HIB27		Grid Reference	TL 0907 4689	
			E	N	
Structure Name	SOUTHILL ROAD RAILWAY BRIDGE		Location (Parish)	CARDINGTON	
Date of Inspection	20 MAR 2002		Type of Inspection	G	
				P	
				✓	
				S	
			Inspected by		
			Overall Assessment	G	
				F	
				P	✓
			From Span	1	To Span
				1	1

Defect Assessment

[illegible]

Defect Assessment (Cont.)

15. Jack arches									
16. Arch ring/Corrugated Metal	C	4	R	H				CRACKS. HOLLOW BRICKWORK. POOR JOINTS.	
17. Spandrels	D	3	R	H				CRACKS. BULGING. MOVEMENT.	
18. Tie rods									
19. Drainage Systems			B					MINOR SEEPAGE/DAMP AREAS.	
20. Waterproofing			A					SEEPAGE.	
21. Surfacing	B	2	N					MINOR SETTLEMENT. CRACK.	
22. Service Ducts									
23. Expansion Joints									
24. Parapets/Handrails	D	3	R	H				SPALLING. POOR JOINTS. VEGETATION.	
25. Access gantries or walkways									
32. Dry Stone Walls									
33. Troughing									

Reason for priority allocation

- 06 WINGWALLS
- 16 ARCH RING
- 17 SPANDRELS
- 20 WATERPROOFING
- 24 PARAPETS
- Remove vegetation, replace spalled/hollow brickwork and repoint to prevent further deterioration.
- Remove roots/repoint joints in intrados and replace brickwork in arch ends to prevent further deterioration.
- Install RC backing to spandrels to prevent further movement.
- Consider installing waterproofing to prevent water ingress.
- Replace spalled brickwork and repoint to prevent further deterioration and restore strength.

Signed

Name

Date

Southill Road Railway Bridge No. HIB27

2.00 Inspection

2.01 Foundations

2.01.1 There are no record drawings available. The foundations are assumed to be spread footings.

2.01.2 There would not appear to be any foundation defects.

2.02 Invert

2.02.1 There are no record drawings available. From inspection the invert is of soil (see plates 1 and 2).

2.02.2 The invert has some debris present, including the missing copings from the parapet, and there is evidence of fires adjacent to the abutments (see plates 1-5).

2.05 Abutments

2.05.1 There are no record drawings available. From inspection the abutments are of brick (see plates 1-5).

2.05.2 The south abutment has a vertical hairline crack 0.85m from the east end for much of the height. There is a diagonal hairline crack from the stringcourse 0.6m from the east end running down to the abutment end at half height then horizontally into the east face and pilaster 1-2mm wide. There is a large area of hollow sounding brickwork west of centre, which may be fire damage. There is some spalled and hollow sounding brickwork to the east end base. The west face has a horizontal crack 1mm at the base plinth and a horizontal hairline crack at the springing, both extending into the pilaster. The pilaster has a further horizontal crack 1-2mm wide towards the top (see plates 3 and 4).

2.05.3 The north abutment has a vertical hairline crack west of centre for the full height extending into the arch. There is a vertical crack towards the west end at half height which extends horizontally to the west end just above the base plinth at 1mm wide. The west end has some ivy growth. The east end has two vertical hairline cracks over the centre, one running horizontally at half height into the east face and pilaster, joining a vertical hairline crack. The east end brickwork is spalled and hollow sounding and has seepage deposits. The east face has a horizontal crack 1-2mm wide at springing level running through the pilaster and vertically up the wingwall joint. The west pilaster is overgrown with ivy (see plates 5 and 6).

Southill Road Railway Bridge No. HIB27

2.00 Inspection

2.06 Wingwalls

2.06.1 There are no record drawings available. From inspection the wingwalls are of brick (see plates 7-9)

2.06.2 The southeast wingwall/pilaster joint is cracked at the top 1mm wide. The top of the wall has much ivy growth. The centre has an area of surface spalling and hollow sounding brickwork, some spalling up to 100mm deep and a slight bulge. The base adjacent to the abutment has spalling up to 100mm deep (see plate 7)

2.06.3 The southwest wingwall has a diagonal hairline crack emanating from the abutment joint at springing level running down towards the base. There is a horizontal crack at half height 2mm wide from the centre to the copings. The central area is bulging and hollow sounding (see plate 8).

2.06.4 The northwest wingwall is covered in ivy (see plate 9).

2.06.5 The northeast wingwall has a spalled area adjacent to the abutment just above half height. There are some surface spalled bricks and poor joints present.

2.08 Approach Embankments

2.08.1 There are no record drawings available. From inspection the bridge has approach embankments to both sides (see plates 1, 2 and 10).

2.08.2 The embankments are heavily overgrown in places with numerous trees growing, some adjacent to the bridge (see plates 1, 2 and 10).

Southill Road Railway Bridge No. HIB27

2.00 Inspection

2.16 Arch Ring

2.16.1 There are no record drawings available. From inspection the arch is of 4-ring brick construction 460mm thick (see plates 1, 2 and 11).

2.16.2 The arch west face original brickwork over the crown between the blue brick facing is all hollow sounding, cracked, spalled and loose. The face north of the crown is bulging 10mm. There is a crack around the barrel running from the south abutment at hairline wide, over the south $\frac{1}{4}$ point at 5mm wide, over the crown at hairline wide, over the north $\frac{1}{4}$ point at 3-4mm wide and finishing near the north abutment at hairline wide (see plates 11-16).

2.16.3 The arch intrados has a longitudinal crack 200mm from the west face, hairline at the north abutment, 3-4mm at the north $\frac{1}{4}$ point, 10mm at the south $\frac{1}{4}$ point and hairline at the south abutment. There is a crack running parallel 400mm from the face hairline at the crown, 2-3mm over the north $\frac{1}{4}$ point then running diagonally to the north abutment at hairline wide and a short crack 400mm from the face 1-2mm wide towards the south abutment. The west end over the crown has spalled bricks and the brickwork to the south side is hollow sounding. The northwest corner of the intrados has ivy roots in the joints. The west end has seepage deposits to both sides. There is a longitudinal crack at the centre 2-3mm wide running from the north abutment to south of the crown and a longitudinal hairline/0.5mm wide crack 0.6m west of centre from near the north abutment to near the crown. There is an area of eroded joints 20mm deep at the centre towards the north abutment. There is a longitudinal crack 240mm from the east face, hairline wide at the north abutment, 2-3mm at the north $\frac{1}{4}$ point, 3-4mm at the crown, 2-3mm at the south $\frac{1}{4}$ point then 440mm from the face running to the south abutment 2-3mm wide. The east end has seepage deposits to both sides and there is an area of spalled and hollow sounding brickwork at the south abutment (see plates 12, 14, 16-18, 20, 22 and 26).

2.16.4 The arch east face has a crack around the barrel running from the north abutment to the north $\frac{1}{4}$ point 1mm wide and from the south abutment to the south $\frac{1}{4}$ point 1mm wide. There is some bulging with the spandrel wall over the south $\frac{1}{4}$ point (see plates 19-26).

Southill Road Railway Bridge No. HIB27

2.00 Inspection

2.17 Spandrels

2.17.1 There are no record drawings available. From inspection the spandrels are of brick (see plates 1 and 2).

2.17.2 The west spandrel/arch barrel joint is cracked from the south abutment at hairline wide, over the south $\frac{1}{4}$ point at 5mm wide, over the crown at hairline wide and at the north $\frac{1}{4}$ point 3-4mm wide, extending towards the north abutment at hairline wide. At the north $\frac{1}{4}$ point there is a horizontal crack 1-2mm wide running from the arch barrel/spandrel joint to the pilaster. The south side has a vertical crack south of the $\frac{1}{4}$ point from the arch barrel at hairline wide to the parapet stringcourse 2-3mm wide. There is a vertical hairline crack at the south pilaster joint from the parapet stringcourse to half height and continuing horizontally into the pilaster. The north end of the spandrel has ivy growth (see plates 12-15).

2.17.3 The east spandrel has a crack around the barrel running from the north abutment to the north $\frac{1}{4}$ point 1mm wide. The barrel/spandrel joint is cracked from the south abutment to the south $\frac{1}{4}$ point 1mm wide then vertically up through the spandrel. The south side has a horizontal crack 1mm wide at half height and a vertical crack 4-5mm wide at the south end. The south side is bulging. The north side has some bulging and an area of eroded joints 20mm deep (see plates 19-26).

2.19 Drainage Systems

2.19.1 There are no record drawings available. From inspection there are no drainage weep-pipes visible.

2.19.2 The abutments have some minor seepage deposits and the wingwalls have some damp patches along the base.

2.20 Waterproofing

2.20.1 There are no record drawings available. The waterproofing could not be inspected.

2.20.2 The arch has seepage deposits at both ends (see plates 17 and 18).

Southill Road Railway Bridge No. HIB27

2.00 **Inspection**

2.21 Surfacing

2.21.1 There are no record drawings available. From inspection the surfacing is 4.65m wide and there are soft verges to both sides (see plates 27 and 28).

2.21.2 The carriageway has a wide trench reinstatement over the east side. There is minor cracking across the west side of the carriageway at the south end. The west carriageway edge has slight settlement up to 10mm at both ends of the parapet (see plates 27 and 28).

2.24 Parapets

2.24.1 There are no record drawings available. From inspection the parapets are of brick (see plates 1, 2, 27 and 28).

2.24.2 The west parapet has some spalled bricks and poor joints and has ivy growth to the ends. The north pilaster brickwork has cracking and is dislodged 20mm (see plates 2, 13 and 27-29)

2.24.3 The east parapet has much spalling and poor joints, with much ivy growth in the joints. The north pilaster has a vertical crack 1mm wide and there are missing copings adjacent to the wall. The south end has some bulging with the spandrel wall below and there is vegetation growth at the south pilaster. There is a diagonal crack 1mm wide to the road face adjacent to the south pilaster (see plates 1, 19-21, 25, 27, 28 and 30).

Southill Road Railway Bridge No. HIB27

3.00 Conclusions

- 3.01 The bridge is in poor condition and has spandrel movement and longitudinal cracks at the arch ends.
- 3.02 The spalled brickwork and poor joints in the abutments would appear to be due to weathering and ivy growth, which is made worse by the seepage present. The hollow sounding brickwork may be due to fire damage, as the walls have evidence of fires adjacent. The defects do not appear severe at present. The vertical crack at the north abutment centre may indicate there is some movement to the abutment, but this would not appear excessive. The cracking at the abutment ends may be due to some movement to the abutment and wingwalls and possibly the movement of the spandrels and arch ends.
- 3.03 The spalled brickwork and poor joints in the wingwalls would appear to be due to weathering and ivy growth, which should be repaired to prevent further deterioration.
- 3.04 The approach embankments are overgrown but this would not appear to be causing distress to the structure.
- 3.05 The arch intrados longitudinal cracking at the arch ends indicates both spandrels are moving, taking the arch ends with them. The longitudinal cracking at the centre may indicate there is some movement to the arch and north abutment.
- 3.06 The cracking and bulging to the east spandrel indicates movement has taken place. The longitudinal cracking at the arch ends indicates both spandrels are moving, taking the arch ends with them. The spandrels require strengthening, possibly with reinforced concrete backing, to prevent further movement and damage to the structure.
- 3.07 The seepage in the arch indicates the waterproofing is ineffective. The water ingress may be causing the spalling and poor joints present. Waterproofing should be considered to prevent the water ingress.
- 3.08 The surfacing defects are minor only and do not require repair at the present time.
- 3.09 The east parapet has many open joints and spalled bricks, which would appear to have been caused by the growth of ivy along the wall, there still being many roots in the joints. The wall requires repointing, and the spalled and missing brickwork and copings replacing, to restore the parapet strength. The dislodged brickwork to the west parapet end appears to be due to vehicle impact. The wall requires the dislodged section rebuilding and the ivy growth removing and joints repointed.

Southill Road Railway Bridge No. HIB27

4.00 Recommendations

4.06 Wingwalls

4.06.1 Remove vegetation, replace spalled/hollow brickwork and repoint to prevent further deterioration.

4.16 Arch Ring

4.16.1 Remove ivy roots from the west end of the arch intrados and repoint joints to prevent further deterioration.

4.16.2 Replace brickwork to arch faces to prevent further deterioration.

4.17 Spandrels

4.17.1 Install RC backing to spandrels to prevent further movement.

4.20 Waterproofing

4.20.1 Consider installing waterproofing to prevent water ingress.

4.24 Parapets

4.24.1 Remove ivy roots from the parapet brickwork, repoint joints, and replace spalled and displaced/missing bricks and copings to prevent further deterioration and restore parapet strength.

Signed

Date:

Name:

Signed

Date:...

Name:

Southill Road Railway Bridge No. HIB27

Appendix A

Photographs

Plate 1	East elevation.
Plate 2	West elevation.
Plate 3	South abutment.
Plate 4	South abutment west end.
Plate 5	North abutment.
Plate 6	North abutment east end.
Plate 7	Southeast wingwall.
Plate 8	Southwest wingwall.
Plate 9	Northwest wingwall.
Plate 10	South approach embankment.
Plate 11	Elevation through arch from the west side.
Plate 12	Arch and north abutment west end.
Plate 13	Arch west face north side.
Plate 14	Arch west end over north abutment.
Plate 15	Arch west face and spandrel south side.
Plate 16	Arch west end over south abutment.
Plate 17	Arch north side.
Plate 18	Arch south side.
Plate 19	Elevation through arch from the east side.
Plate 20	Arch east face and spandrel south side.
Plate 21	Arch east face, spandrel and parapet south side.
Plate 22	Arch and south abutment east end.
Plate 23	Arch east face and spandrel south side.
Plate 24	East spandrel south end.
Plate 25	Arch east face and spandrel north side.
Plate 26	Arch and north abutment east end.
Plate 27	Carriageway elevation from the south.
Plate 28	Carriageway elevation from the north.
Plate 29	West parapet north end.
Plate 30	East parapet north end.

Southill Road Railway Bridge No. HIB27



Plate 1
East elevation




Plate 2
West elevation

Southhill Road Railway Bridge No. HIB27



Plate 3
South abutment




Plate 4
South abutment west end

Southhill Road Railway Bridge No. HIB27




Plate 5
North abutment




Plate 6
North abutment east end

Southill Road Railway Bridge No. HIB27



Plate 7
Southeast wingwall




Plate 8
Southwest wingwall

Southill Road Railway Bridge No. HIB27




Plate 9
Northwest wingwall



Plate 10
South approach embankment

Southill Road Railway Bridge No. HIB27



Plate 11
Elevation through arch from the west side




Plate 12
Arch and north abutment west end

Southill Road Railway Bridge No. HIB27




Plate 13
Arch west face north side




Plate 14
Arch west end over north
abutment

Southill Road Railway Bridge No. HIB27




Plate 15
Arch west face and spandrel
south side



Plate 16
Arch west end over south
abutment

Southill Road Railway Bridge No. HIB27




Plate 17
Arch north side




Plate 18
Arch south side

Southhill Road Railway Bridge No. HIB27



Plate 19
Elevation through arch from
the east side




Plate 20
Arch east face and spandrel
south side

Southill Road Railway Bridge No. HIB27




Plate 21

Arch east face, spandrel and
parapet south side




Plate 22

Arch and south abutment
east end

Southill Road Railway Bridge No. HIB27



Plate 23
Arch east face and spandrel
south side



Plate 24
East spandrel south end

Southill Road Railway Bridge No. HIB27



Plate 25
Arch east face and spandrel
north side.




Plate 26
Arch and north abutment east
end

Southhill Road Railway Bridge No. HIB27




Plate 27
Carriageway elevation from the south




Plate 28
Carriageway elevation from the north

Southill Road Railway Bridge No. HIB27



Plate 29
West parapet north end





Plate 30
East parapet north end

Southill Road Railway Bridge No. HIB27


Appendix B

Defects Drawings

Drawing Number	Title
HIB27/6	Elevations Defects
HIB27/7	Arch Defects
HIB27/8	Abutment Defects
HIB27/9	Carriageway Defects



EAST ELEVATION




WEST ELEVATION

Drawing Number

HIB27/06

Notes



hollow



eroded joints



ivy

Do not scale this drawing


Rev	Date	Checked

Babtie


Client	BEDFORDSHIRE COUNTY COUNCIL
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON EAST & WEST ELEVATION DEFECTS

Drawing No.	HIB27/06	Date	APRIL 2002
Scale	1:100	Drawn	SR
		Checked	PDB
		Approved	<i>[Signature]</i>


Copyright reserved
Babtie Group Ltd
Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY



Drawing Number		HIB27/07	
Notes			
	seepage		
	hollow		
	spalled		
	eroded joints		
	ivy		
Do not scale this drawing			
Rev	Date	Checked	
Babtie			
Client	BEDFORDSHIRE COUNTY COUNCIL		
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES		
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON ARCH DEFECTS		
Drawing No.	HIB27/07		
Scale	1:50	Date	APRIL 2002
Drawn	SR	Checked	PDS
Approved			
Copyright reserved Babtie Group Ltd Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY			



NORTH ABUTMENT



SOUTH ABUTMENT


Drawing Number

HIB27/08

Notes



Seepage



Spalling



Ivy

Do not scale this drawing


Rev	Date	Checked

Babtie

Client	BEDFORDSHIRE COUNTY COUNCIL
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON ABUTMENT DEFECTS

Drawing No.	HIB27/08				
Scale	1:100	Date	APRIL 2002		
Drawn	SR	Checked	PDB	Approved	

Copyright reserved
Babtie Group Ltd
Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY



Drawing Number

HIB27/09

Notes

Do not scale this drawing

Rev	Date	Checked

Babtie

Client	BEDFORDSHIRE COUNTY COUNCIL		
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES		
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON CARRIAGEWAY DEFECTS		
Drawing No.	HIB27/09	Date	APRIL 2002
Scale	1:100	Drawn	SR
	Checked	PDB	Approved

Copyright reserved
Babtie Group Ltd
Box 272, The Merton Centre, 45 St.Peters Street, Bedford MK40 2ZY

Southill Road Railway Bridge No. HIB27

Appendix C

Statutory Undertakers Apparatus Information

There is no information regarding Statutory Undertakers Apparatus.

Southill Road Railway Bridge No. HIB27

Appendix D

Survey Drawings

Sheet 1 Structure Dimensions

Drawing Number Title

HIB27/1 Plan and Levels

HIB27/2 East Elevation

HIB27/3 West Elevation

HIB27/4 Cross section 1


Southill Road Railway Bridge No. HIB27

Appendix D

Sheet 1

Structure Dimensions

Structural Element	Surveyed Dimension
Skew Span	8.49
Skew	21°
Ring Thickness	0.46
Width between parapets	6.03
Carriageway width	Varies - approx. 4.65
West verge	Varies - approx. 0.73
East verge	Varies - approx. 0.65
Parapet Width	0.34



DATUM=26.000

CHAINAGE	5.000	6.000	7.000	8.000	9.000	10.000	11.000	12.000	13.000	14.000	15.000	16.000	17.000	18.000
GROUND	31.728 31.909 32.021		26.821 26.775	26.714		26.701		26.642		26.635		26.729 26.887 27.058	32.060 31.765	
ARCH			29.764 30.269	30.947	31.227	31.541		31.712 31.705	31.618	31.510	31.289 30.996 30.832 30.655	30.112 29.860		
EDGE OF CARRIAGEWAY	32.020		32.210		32.328		32.392		32.421		32.320		32.224 32.188	
PARAPET	33.708	33.779	33.698	33.730	33.741	33.749		33.725		33.682	33.752	33.681		

Drawing Number

HIB27/2

Notes

1.
All levels are related to the OSBM
on Southill Road Railway Bridge
Value 33.710m
2.
Direction of elevation is perpendicular to
the face of the structure

Do not scale this drawing


Rev	Date	Checked

Babtie

Client	BEDFORDSHIRE COUNTY COUNCIL
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON EAST ELEVATION

Drawing No.	HIB27/2				
Scale	HS=1:100 VS=1:100	Date	FEB 2002		
	Drawn DMS	Checked		Approved	

Copyright reserved
Babtie Group Ltd 95 Bothwell Street, Glasgow G2 7HX



Drawing Number

HIB27/3

Notes

1.
All levels are related to the OSBM
on Southill Road Railway Bridge
Value 33.710m
2.
Direction of elevation is perpendicular to
the face of the structure

Do not scale this drawing

Rev Date Checked

Babtie

Client
BEDFORDSHIRE
COUNTY COUNCIL

Project
ASSESSMENT OF BRITISH RAIL
PROPERTY BOARD STRUCTURES

Title
SOUTHILL ROAD RAILWAY BRIDGE
U147 CARDINGTON
WEST ELEVATION

Drawing No. HIB27/3

Scale HS=1:100 VS=1:100

Drawn DMS Checked Approved

Copyright reserved
Babtie Group Ltd 95 Bothwell Street, Glasgow G2 7HX

Drawing Number

HIB27/4

Notes

1.
All levels are related to the OSBM
on Southill Road Railway Bridge
Value 33.710m


Do not scale this drawing

Rev	Date		Checked	

Babtie

Client	BEDFORDSHIRE COUNTY COUNCIL			
Project	ASSESSMENT OF BRITISH RAIL PROPERTY BOARD STRUCTURES			
Title	SOUTHILL ROAD RAILWAY BRIDGE U147 CARDINGTON CROSS SECTION 1			
Drawing No.	HIB27/4			
Scale	HS=1:50 VS=1:50		Date	FEB 2023
	Drawn	DMS	Checked	Approved

Copyright reserved
Babtie Group Ltd 95 Bothwell Street, Glasgow G2 7HX



DATUM=31.000									
CHAINAGE	-3.612	-3.282	-2.741	-2.492	-0.000	-2.511	-2.817	-3.184	-3.519
SECTION 1	33.756	32.615	32.468	32.398	32.406	32.394	32.493	32.499	33.743
SOFFIT	31.683								31.711

Southill Road Railway Bridge No. HIB27

Appendix E

List of Record Drawings

None

Southill Road Railway Bridge No. HIB27

Appendix F

Site Factors Affecting Assessment

Arch Profiles and Assessment Data

Sheet 1 Parameters for Assessment

Sheet 2 Carriageway Profile and Statutory Undertakers Plant

Southill Road Railway Bridge No. HIB27

Appendix F

Sheet 1 Parameters for Assessment

Arch Barrel Material and Condition	
Arch Barrel Material	
Brick 4-ring (460mm). Not engineering bricks but appear of good quality.	
Arch Barrel Material Condition	
Good condition generally but has some spalled bricks.	
Arch Barrel General Condition	
Longitudinal crack at centre. Large longitudinal cracks at both ends. Intrados brickwork in sound condition apart from ends and arch appears to have a good shape.	
Fill Material	
Well compacted. Minor settlement.	
Mortar Joints	
Joint Width	
Less than 10mm	
Joint Condition	
Generally good condition but has some patches of eroded joints up to 20mm deep. Some ivy growth to northwest corner.	
Depth missing	
20mm	
Factors for assessment	
Barrel Factor F_b	1.0
Fill Factor F_f	0.7
Joint Width Factor F_w	0.9
Mortar Factor F_{mo}	1.0
Joint Depth Factor F_d	0.9
Condition Factor F_{cm}	0.6
Arch Profile	
The arch elevation surveys show that the arch appears to have a uniform circular profile.	

Southill Road Railway Bridge No. HIB27

Appendix F

Sheet 2 Carriageway Profile and Statutory Undertakers Plant

Affect of Carriageway Profile

Lift-off: Lift-off will be considered in the assessment, as the carriageway over the structure is curved.

Centrifugal Effects: Centrifugal effects are not considered in the assessment. The carriageway over the structure is nearly straight.

Affect of Statutory Undertakers Apparatus

No information is available on existing services.

Southill Road Railway Bridge No. HIB27

Appendix G

AIP Form