

**BRB (Residuary) Ltd**

**Major Works Programme 2009 - 2012**

**VAR9/2932 ASSESSMENT PROGRAMME**

**BE4 ASSESSMENT AND INSPECTION REPORT**

**Mill Tack Road Bridge  
Nr Turriff, Aberdeenshire**

**BRIDGE REF: IMD/433**



**December 2010**

**Document control sheet** **BPP 04 F8**

Client: BRB (Residuary) Ltd  
 Project: Major Works Programme 2009/2012 Job No: B12360BB  
 Document Title: VAR9/2932 Assessment Programme  
 BE4 Assessment: IMD/433

|                                   | Originator | Checked by | Reviewed by | Approved by |
|-----------------------------------|------------|------------|-------------|-------------|
| <b>ORIGINAL</b><br><b>Form AA</b> | NAME       | NAME       | NAME        | NAME        |
|                                   |            |            |             |             |
| DATE<br><b>6 Sept 2010</b>        | SIGNATURE  | SIGNATURE  | SIGNATURE   | SIGNATURE   |
| <b>Document Status</b>            |            |            |             |             |

|                                   |           |           |           |           |
|-----------------------------------|-----------|-----------|-----------|-----------|
| <b>REVISION</b><br><b>Form BA</b> | NAME      | NAME      | NAME      | NAME      |
|                                   |           |           |           |           |
| DATE<br><b>22 Dec 2010</b>        | SIGNATURE | SIGNATURE | SIGNATURE | SIGNATURE |
| <b>Document Status</b>            |           |           |           |           |

|                        |           |           |           |           |
|------------------------|-----------|-----------|-----------|-----------|
| <b>REVISION</b>        | NAME      | NAME      | NAME      | NAME      |
| DATE                   | SIGNATURE | SIGNATURE | SIGNATURE | SIGNATURE |
| <b>Document Status</b> |           |           |           |           |

*Jacobs Engineering U.K. Limited*

This document has been prepared by a division, subsidiary or affiliate of *Jacobs Engineering U.K. Limited* ("Jacobs") in its professional capacity as consultants in accordance with the terms and conditions of Jacobs' contract with the commissioning party (the "Client"). Regard should be had to those terms and conditions when considering and/or placing any reliance on this document. No part of this document may be copied or reproduced by any means without prior written permission from Jacobs. If you have received this document in error, please destroy all copies in your possession or control and notify Jacobs.

Any advice, opinions, or recommendations within this document (a) should be read and relied upon only in the context of the document as a whole; (b) do not, in any way, purport to include any manner of legal advice or opinion; (c) are based upon the information made available to Jacobs at the date of this document and on current UK standards, codes, technology and construction practices as at the date of this document. It should be noted and it is expressly stated that no independent verification of any of the documents or information supplied to Jacobs has been made. No liability is accepted by Jacobs for any use of this document, other than for the purposes for which it was originally prepared and provided. Following final delivery of this document to the Client, Jacobs will have no further obligations or duty to advise the Client on any matters, including development affecting the information or advice provided in this document.

This document has been prepared for the exclusive use of the Client and unless otherwise agreed in writing by Jacobs, no other party may use, make use of or rely on the contents of this document. Should the Client wish to release this document to a third party, Jacobs may, at its discretion, agree to such release provided that (a) Jacobs' written agreement is obtained prior to such release; and (b) by release of the document to the third party, that third party does not acquire any rights, contractual or otherwise, whatsoever against Jacobs and Jacobs, accordingly, assume no duties, liabilities or obligations to that third party; and (c) Jacobs accepts no responsibility for any loss or damage incurred by the Client or for any conflict of Jacobs' interests arising out of the Client's release of this document to the third party.

## Contents

|            |   |            |
|------------|---|------------|
| <b>1</b>   | <b>General Description and Structural Details</b> | <b>1-1</b> |
| 1.1        | Introduction                                      | 1-1        |
| 1.2        | Location and General Description                  | 1-1        |
| 1.3        | Construction type                                 | 1-1        |
| <b>2</b>   | <b>Existing Information Search</b>                | <b>2-1</b> |
| 2.1        | Services Search                                   | 2-1        |
| 2.2        | SI Results  | 2-1        |
| 2.3        | Existing Drawings                                 | 2-1        |
| <b>3</b>   | <b>Structure Condition</b>                        | <b>3-1</b> |
| 3.1        | General   | 3-1        |
| 3.2        | Main superstructure                               | 3-1        |
| 3.2.1      | Girders   | 3-1        |
| 3.2.2      | Concrete jack arches                              | 3-1        |
| 3.3        | Abutments   | 3-1        |
| 3.4        | Wingwalls   | 3-1        |
| 3.5        | Parapets  | 3-1        |
| 3.6        | Formation   | 3-2        |
| 3.7        | Road Surface                                      | 3-2        |
| <b>4</b>   | <b>Assessment to BE4</b>                          | <b>4-1</b> |
| 4.1        | Structural Parts checked to BE4                   | 4-1        |
| 4.2        | Methodology                                       | 4-1        |
| 4.3        | Results   | 4-1        |
| <b>5</b>   | <b>Conclusions and Recommendations</b>            | <b>5-1</b> |
| Appendix A | Photographs                                       |            |
| Appendix B | Service search                                    |            |
| Appendix C | Trial pit log                                     |            |
| Appendix D | Form AA   |            |
| Appendix E | Form BA   |            |
| Appendix F | Calculations                                      |            |

### **1.1 Introduction**

Jacobs was appointed by BRB(R) to conduct the site survey at IMD/433 in sufficient detail to provide data for BE4 assessment work.

Metal samples were not taken from this bridge; the date of reconstruction (1938) and welding of the parapet posts to the edge girders indicate that the girders are constructed from mild steel. Structural Soils Ltd. excavated a trial pit in the road over the first internal girder from the north edge in order to confirm girders dimensions and infill properties.

### **1.2 Location and General Description**

Bridge IMD/433 carries an unclassified road over the track bed of the former Macduff to Inveramsay railway about 7 km south north of Turriff in Aberdeenshire.

The road is a single carriageway 2.74m wide with 0.77m wide soft verges both sides (photos 3&4). The national speed limit of 60mph applies although practical speeds are severely limited by the road geometry. Only occasional light vehicles were observed on the road at the time of inspection.

The OS grid reference is NJ728573.

The bridge deck was reconstructed in 1938; the abutments probably date from the opening of the railway in 1860.


### **1.3 Construction type**

The structure is a single square span overbridge with a clear span of 4.57m (15' – 0") between abutment faces (Photos 1 and 2).

The bridge comprises of six longitudinally spanning RSJs, spaced at 3ft (0.914m) centres. Pre-cast concrete jack arches span between the bottom flanges of the girders. There is concrete infill covering the girders and jack arches. All girders are supported on granite bearing stones. Additional angles are riveted to the top flange of the edge girders to retain the concrete infill and support the parapet metal posts.

The parapets are timber palings supported on the vertical metal angles that are welded to the edge girders.

The abutments and wingwalls are constructed from squared large granite blocks, regularly coursed.



Edge girder details

## 2 Existing Information Search

### 2.1 Services Search

Documentation obtained by Structural Soils Ltd is included in Appendix B.

### 2.2 SI Results

A trial pit was excavated as part of the survey located at the edge of the carriageway to expose the top flange of the first internal girder from the north.

Data on the trial pit is included in Appendix C.

### 2.3 Existing Drawings

There are no existing drawings for the reconstructed bridge.

## 3 Structure Condition

### 3.1 General

The survey and inspection for BE4 assessment were undertaken on Monday 12 July 2010. Weather conditions were partially cloudy with temperature about 16°C.

Parking was available on the soft verge to the south east of the bridge. Access to the formation was gained through a gap in the fence and down the steep slope at the back of the north west wingwall.

### 3.2 Main superstructure

#### 3.2.1 Girders

The girders are in fair condition. There is some surface corrosion and loss of section, estimated to be a maximum of 5% of the bottom flange thickness to all girders. There is also some flaking at the east end of the north edge girder about 2 to 3 inches from concrete bearing stones (photo 8). There is flaking corrosion on the exposed face of the north edge girder. Green paint on the girders is still present but it is largely ineffective (photo 5).

#### 3.2.2 Concrete jack arches

The pre-cast concrete jack arches are in good condition with no visible cracking or dampness (photo 5).

### 3.3 Abutments

The abutments are constructed from squared large granite blocks, regularly coursed. The quoins are constructed from red sandstone blocks. The abutments are in good condition with no significant defects (photos 6 and 7). They are considered to be adequate for full BE4 Construction and Use loading.

### 3.4 Wingwalls

The wingwalls lie parallel with the road and are constructed from regularly coursed squared granite blocks (photos 6 and 7). They are generally in good condition. There is a 2-3mm wide crack running through the mortar courses, starting from top of the north west parapet close to the east end and stretching vertically to near embankment level at foot of the north west wingwall.

### 3.5 Parapets

The parapets on the bridge deck are timber paling fences supported by metal angles that are welded to the edge girders. They are generally in good condition though with some paint loss throughout.

The parapets over the wingwalls are constructed from regularly coursed squared granite blocks. They are generally in very good condition. One coping stone at the west end of the north west parapet is slightly dislocated (photo 9).

**3.6 Formation**

The formation is overgrown. A 1.2m high brick wall has been constructed between the abutments at the south end of the bridge opening (photo 1).

**3.7 Road Surface**

The road surface is in good condition (photos 3&4).

## 4 Assessment to BE4

### 4.1 Structural Parts checked to BE4

The following parts of the bridge were checked to BE4:

- Internal girders: Bending and shear for dead and live load
- Edge girders: Bending and shear for dead load.

The abutments were assessed qualitatively.

### 4.2 Methodology

Capacities of the girders were calculated using estimates of reduced section sizes where corrosion is present. A general condition factor was not applied.

The bridge complies with the construction types listed in BE4 Clause 303 (c) (i.e Jack arches), which allowed the quick assessment method to be used on the internal girders.

The four internal girders attracting live loading were checked for full 24 ton C&U loading.

The concrete deck construction offers restraint to the top flanges of the internal girders against lateral torsional buckling; therefore effective length was taken as zero.

The edge girders are separated from the carriageway by an intervening girder and therefore are not required to be assessed for live loads. They were checked for dead load effects only.

Review of the adequacy of the jack arches were based upon the empirical method described in Bridgeguard 3 Current Information Sheet No 22 (Pro-forma for the empirical assessment of brick, masonry and concrete jack arches and associated ties.)

The abutments were assessed qualitatively.

### 4.3 Results

#### Element: Internal girders under full carriageway loading (mid-span)

| Action  | Location | Dead load effect | Full C&U load effect | Total load effect | Assessed resistance | Live load capacity |
|---------|----------|------------------|----------------------|-------------------|---------------------|--------------------|
| Bending | Mid-span | 9.4 ton.ft       | 14.5 ton.ft          | 23.9 ton.ft       | 101.2 ton.ft        | Full C&U loading   |
| Shear   | Support  | 2.5 tons         | 10 tons              | 12.5 tons         | 33.2 tons           | Full C&U loading   |

**Element: Edge girder (no live load imposed).**

| Action  | Location | Dead load effect                                   | Full C&U load effect | Total load effect | Assessed resistance | Load capacity |
|---------|----------|--|----------------------|-------------------|---------------------|---------------|
| Bending | Mid-span | 5.39 ton.ft  | 0 ton.ft             | 5.39 ton.ft       | 85.23 ton.ft        | Pass          |
| Shear   | Support  | Less onerous than internal girder shear conditions |                      |                   |                     | Pass          |

**Element: Jack Arches and Tie Bars**

The empirical assessment of the jack arches indicates one non-compliance, namely: the tie bars are located within the crown of the external jack arches.

**Element: Substructure**

The abutments show no signs of structural distress. By qualitative assessment, they appear to be satisfactory for Full C&U loading.

The assessment demonstrates that the main girders are capable of sustaining full C&U loading in accordance with BE4 requirements even after making due allowance for corrosion.

The empirical assessment of the jack arches indicates a non-compliance with the tie bars being located within the crown of the external jack arches. There is however adequate tie bar provision and there are no concerns about corrosion as they are protected by the concrete. There is also concrete infill over the jack arches therefore the arch/tie/fill configuration is unlikely to lead to rotation of the edge girders. There are no indications of any movement having occurred. It is therefore concluded that the jack arches are adequate for loading commensurate with the capacity of the girders.

The paint system is breaking down particularly on the exposed webs of the edge girders. Early maintenance would be beneficial to prevent further deterioration.

The bridge deck parapets comprise simple wooden paling fences, which would have negligible vehicle containment capacity. A coping stone at the west end of the north parapet has been dislocated and needs re-setting.

Appendix A Photographs



1. North elevation



2. South elevation



3. Road looking East



4. Road looking west



5. Soffit and north edge girder



6. East abutment and North east wingwall



7. West abutment and North west wingwall



8. East end of north edge girder



9. Dislocated coping stone at north west parapet



10. Trial pit at north verge mid-span

**Appendix B Service search**



95 Kilbirnie Street,  
Glasgow G5 8JD.

Our Ref: SC/10.06.10/MS075/1/101000

Your Ref: EQ/XTCAE577

Date: 10 June 2010

, .

National One Call  
1 Mill Place  
Mill Road Industrial Estate  
Linlithgow Bridge  
West Lothian, EH49 7TL.

Fax: ~

Email: ~

**24 hour gas escape  
number 0800 111 999**

Calls will be recorded and  
may be monitored.

Dear Sir / Madam,

**Re: Proposed Works Enquiry at: Railway Structure Mains Of Blackton, South Of Macduff.**

Scotland Gas Networks acknowledges receipt of your notice of your intention to carry out work at the above location.

**According to our records Scotland Gas Networks has no gas mains in the area of your enquiry.**

**Gas pipes owned by other Gas Transporters and also privately owned may be present in this area. Information with regard to such pipes should be obtained from the owners.**

If you have any further enquires please contact the Telephone number below.

Yours faithfully,

  
Admin Assistant  
0141 418 4093

Scotland Gas Networks  
Registered in Scotland No SC264065  
Registered Office: Inveralmond House, 200 Dunkeld  
Road, Perth PH1 3AQ



This copy has been made by or with the authority of Scottish and Southern Energy plc. Under the Copyright, Designs and Patents Act 1988 (the Act), unless the Act provides a relevant exception to copyright, the copy must not be copied without prior permission from the copyright owner.  
BASED UPON THE DATA PROVIDED BY THE NATIONAL ARCHIVE OF THE CONTROLLER OF H.M. STATISTICAL OFFICE, CROWN COPYRIGHT RESERVED. SSSI DATA (c) Scottish Natural Heritage.  
Scottish and Southern Energy plc. Registered in Scotland No. 117118.  
Registered Office: Inverarmad House 200 Dunkeld Road Perth PH1 3AQ

EQ/XTCAE577

Mains of Blackton

NORTH EAST DISTRICT

Tel: 01224 667200

All Voltages

Scale : 1:1250

10/06/2010

NJ72725719

UNCONTROLLED COPY  
Subject to revision without notice.

NORMAL DEPTH TO THE TOP OF THE  
CABLE WHEN LAID.

FOOTPATH      services      iv      by      e.h.v.  
0.40m 0.45m 0.60m 0.75m


ROAD CROSSING 0.65m 0.60m 0.75m 0.90m  
l.v./services - upto 1000V  
h.v. - over 1000V to 11,000V  
e.h.v. - 22,000V and 132,000V

**WARNING**

There may have been subsequent alterations to the surface levels. The user must be taken to determine positions and depths of cables. Danger from Buried Cables - should be established before commencing excavation works (available from HSE)

WHEN WORKING IN THE VICINITY OF CABLES, USE THE HEALTH AND SAFETY GUIDANCE AVAILABLE FROM HSE.

For plots at 1:10000 scale there may be more information visible at 1:500 scale. Responsibility is with the user of this map to check no further information exists at 1:500 scale.



## **Watch it!**

Safety advice brought to you by  
Southern Electric Power Distribution plc and  
Scottish Hydro Electric Power Distribution Ltd

These notes are intended to help all those who have to work in the vicinity of electrical apparatus. Employers have a legal obligation to ensure that their operatives are fully instructed in the correct procedures.

**The Electricity at Work Regulations 1989** impose health and safety requirements upon employers, employees and self-employed persons with respect to electricity at work. The regulations impose restrictions on persons being engaged in work activities on or near live conductors.

**Regulation 14 requires that:** "No person shall be engaged in any work activity on or near any live conductor (other than one suitably covered with insulating material so as to prevent danger) that danger may arise unless:

- ◆ it is **unreasonable** in all circumstances for it to be dead; and
- ◆ it is **reasonable** in all circumstances for him to be at work on or near it while it is live; and
- ◆ suitable precautions (including where necessary the provision of suitable protective equipment) are taken to prevent injury."

The purpose of the regulations is to require precautions to be taken against the risk of death or personal injury from electricity in work activities.

### **Publications**

The Health and Safety Executive have produced a document entitled 'Avoiding Danger from Underground Services', and the Appendix 1 deals specifically with electric cables. Copies are available from HMSO's Accredited Agents and good booksellers, Ref. HS (G) 47.

Copies of Health and Safety Guidance note GS 6 relating to safe working in proximity to overhead lines, are available from HMSO Head Offices of the Federation of Civil Engineering Contractors and the National Federation of Building Trades Employers.

### **Note**

**In situations of emergency or danger, or where the advice contained in these notes cannot be followed, you must consult Scottish and Southern Energy plc immediately. Tel. 08-457 708090 for southern England or 0800 300999 for Scotland.**

**Additional copies of these "Watch it!" leaflets can be obtained from our Mapping Services office upon request. Tel. 01256 337294, or Fax 01256 337295.**

You must read and accept the following safety notes as part of the contract to receive our network plans. You will have the option to print these and issue them to site staff.

### **Watch it! - Working in the vicinity of underground cables.**

Our plans show the positions and normal depths for the buried cables and pipes at the time when they were installed. However, alterations to road alignments surface levels and buildings may have occurred subsequently without our knowledge. If you discover plant or cables that are not marked or incorrectly marked, then you are required to contact us as soon as possible to give us the opportunity to amend our plans.

These plans show the equipment owned by Scottish and Southern Energy plc. There may be other privately owned plant in the area, which is outside of our control. You should always check with the Local Authority, National Grid Company, Department of the Environment, other Electricity Companies and other utilities before proceeding.

It is not intended that the issue of these plans will absolve either party from their obligation under any of the acts that control digging in the public highways.

### **Supplies To Properties, etc.**

The location of cables supplying individual properties, street lighting, traffic signs, telephone kiosks etc. are not always shown on the plans. You should assume that each property, streetlight etc. will have its own supply cable.

### **Major Circuits**

Where our plans indicate the presence of cables with a voltage exceeding 11,000 volts, you are advised to contact our local depot (telephone number is on the plans), before commencing any excavations within the vicinity of these cables. These major transmission circuits form an extremely important link in Scottish and Southern Energy's network, and damaging or modifying these circuits is a major and costly undertaking. Any development should therefore be designed to allow these circuits to remain undisturbed and accessible in their present location.

For your own and your workmates' safety, please follow the **do's** and **don'ts** listed below:

- ✓ **do** make sure you have plans of the underground cables in the area **before** any excavation work starts. Remember that some cables may not be shown on plans. If carrying out emergency work, excavate as though there are buried live cables in the vicinity.
- ✓ **do** use a cable locator to determine the position of existing cables in the work area. The positions should be marked and tests made as work proceeds. **If in doubt, get advice from your supervisor.**
- ✓ **do** ask for a cable to be made dead if it is buried in concrete.
- ✓ **do** watch for signs of cables as work progresses. Note any marker-tape or cable-cover, which may be exposed.

- ✓ **do** backfill carefully, using stone-free soil around the cables, replacing marker-tapes and / or covers.
- ✓ **do** notify us immediately if you accidentally damage our cables. Arrange to keep people well clear of a cable that has been damaged until we have confirmed it has been made safe.
- ✓ **do** make sure before starting to demolish a building that all cables have been disconnected. We welcome prior notice of the intention to demolish buildings. This enables us to ensure that the site has been made safe electrically.
- ✓ **don't** operate a bulldozer, scraper, dragline or excavator; unless you are satisfied that there are no buried cables in the working area.
- ✓ **don't** use picks, pins, forks or pointed instruments in soft clay or soil when cables are present. Exercise extreme caution where such instruments are used to free lumps of stone, or break up firmly compacted ground. **Never** throw a fork or sharp instrument into the ground.
- ✓ **don't** dig trial holes over the indicated route of the cable. Excavate alongside instead.
- ✓ **don't** use exposed cables as a convenient step or handhold.
- ✓ **don't** handle or attempt to alter the position of any cable.

**Remember** that a damaged cable may cause extensive loss of supplies, make expensive repairs necessary and cause serious or even fatal injury.

If effective measures are not adopted to protect our equipment, we will take steps to recover the cost of any damage caused. Persons causing damage resulting in loss of supply to customers can be held legally responsible for any claims made by those customers. Promptness in reporting an incident will minimise costs.

In most cases it is not practicable to make cables dead without interrupting supplies to our customers. But given adequate notice, we will wherever possible, give advice regarding special precautions which may be necessary on any site where particular problems are likely to be encountered. The right is reserved to make a charge for this service.

Electricity cables can exist anywhere - under paths or roads, in gardens or driveways, on new housing or industrial development sites or even farmland.

### **Watch it! - Working in the vicinity of overhead lines**

For your own and your workmates' safety, please follow the **do's** and **don'ts** listed below

- ✓ **do** carefully note the position of all overhead lines before commencing work.
- ✓ **do** co-operate with us during planning and sitework stages.
- ✓ **do** follow the advice given in HSE Guidance Note GS 6 when siting barriers, goal posts, bunting etc.
- ✓ **do** keep overhead lines in view when moving scaffolding or machinery and take special care when felling or lopping trees.
- ✓ **do** remember that the raising or slewing of a crane or excavator jib may cause danger when operating near an overhead line.
- ✓ **do** avoid any machinery that is in contact with an overhead line until we confirm that conditions are safe.
- ✓ **do** warn others to keep well clear.

- ✓ **don't** drive a high vehicle below an overhead line when an alternative route is available.
- ✓ **don't** raise the bed of a tipper lorry beneath an overhead line or drive under the line with the body of the vehicle raised.
- ✓ **don't** steady any suspended load until you are satisfied that there is no danger from overhead lines.
- ✓ **don't** handle or use scaffold platforms, poles, pipes or ladders unless they are at a safe distance from overhead lines.
- ✓ **don't** transport long objects beneath overhead lines, unless they are carried in a horizontal position.
- ✓ **don't** approach or touch any broken or fallen overhead lines.

#### **Always remember that:**

- Electricity can jump gaps.
- Contact or near contact with a crane jib, scaffold or ladder can cause a discharge of electricity with a risk of fatal or severe shock and burns to any person in the vicinity.

If effective measures are not adopted to protect our equipment, we will take steps to recover the cost of any damage caused. Persons causing damage resulting in loss of supply to customers can be held legally responsible for any claims made by those customers. Promptness in reporting an incident will minimise costs.

In most cases it is not practicable to make overhead lines dead without interrupting supplies to customers. However, provided adequate notice is given, then we will, whenever possible, give advice regarding special precautions which may be necessary on site where specific problems may be encountered. The right is reserved to make a charge for this service.

**Appendix C Trial pit log**



|                                      |                          |                            |                             |                                  |  |
|--------------------------------------|--------------------------|----------------------------|-----------------------------|----------------------------------|--|
| Contract:<br><b>BE4 BD21 Bridges</b> |                          | Client:<br><b>Jacobs</b>   |                             | Trialpit:<br><b>IMD/433 TP01</b> |  |
| Contract Ref:<br><b>761587</b>       | Date:<br><b>12.07.10</b> | Ground Level<br><b>---</b> | Co-ordinates:<br><b>---</b> | Sheet:<br><b>1 of 1</b>          |  |

| Samples and In-situ Tests |    |      |         | Water | Backfill | Description of Strata                                | Depth (Thickness) | Material Graphic Legend |
|---------------------------|----|------|---------|-------|----------|--|-------------------|-------------------------|
| Depth                     | No | Type | Results |       |          |  |                   |                         |
|                           |    |      |         |       |          | MADE GROUND: Tarmac.                                 | 0.05              |                         |
|                           |    |      |         |       |          | MADE GROUND: Concrete with 5mm rebar.                | 0.23              |                         |
|                           |    |      |         |       |          | Trial pit terminated at 0.23m depth on steel girder. |                   |                         |

|                              |  |  |  |                    |  |
|------------------------------|--|--|--|--------------------|--|
| Plan (Not to Scale)<br>      |  | <b>General Remarks</b><br>1. Trial hole carried out in north verge.<br>2. Service plans checked and position CAT scanned prior to excavation.<br>3. No groundwater encountered during excavation.<br>4. Trial hole backfilled and reinstated to local authority specification. |  |                    |  |
|                              |  | All dimensions in metres   |  | Scale: <b>1:25</b> |  |
| Method Used: <b>Hand dug</b> |  | Plant Used: <b>Hand tools</b>  |  | Logged By:         |  |
|                              |  |  |  | Checked By:        |  |

GINT\_LIBRARY\_V8\_03.GLBITRIAL PIT LOG - STANDARD | 761587 - BE4 BD21 BRIDGES.GPJ - v8\_03 | 16/07/10 - 12:10 | MP  
 Structural Soils Ltd, Branch Office - Castleford: The Potteries, Pottery Street, Castleford, West Yorkshire, WF10 1NJ. Tel: 01977-552255, Fax: 01977-552299, Web: www.soils.co.uk, Email:north@soils.co.uk.



**Appendix D Form AA**

**FORM 'AA' (BRIDGES)****GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

**APPROVAL IN PRINCIPLE FOR ASSESSMENT (BE4)****Bridge/Line Name: Mill Tack Road Bridge / Inveramsay to Macduff****ELR/Bridge No. IMD/433****Brief Description of Existing Bridge:**

## (a) Span Arrangement

A single span overbridge with a clear span of 15ft (4.57m) between abutment faces and no skew.

## (b) Superstructure Type

The bridge comprises of six longitudinally spanning RSJs, spaced at 3ft (0.914m) centres. Pre-cast concrete jack arches connect the bottom flange of the girders. The girders are surrounded with mass concrete infill.

## (c) Substructure Type

The abutments, wingwalls and pilasters are constructed from squared large granite blocks, regularly coursed. The girders are supported on a course of concrete bearing blocks 50 -75mm thick raising the girders above the stonework.

## (d) Planned highway works/modifications at this site

None

## (e) Road designation class and whether classed as a heavy load route

The road is a single carriageway 2.74m wide with 0.77m wide soft verges both sides. The national speed limit of 60mph applies although practical speeds are severely limited by the road geometry. Principal use is by light vehicles. It is unlikely to be a heavy load route.

## (f) Any other requirements

None

**FORM 'AA' (BRIDGES)****GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

**APPROVAL IN PRINCIPLE FOR ASSESSMENT (BE4)****Assessment Criteria**

## (a) Loadings and Speed

Section sizes used to calculate dead loads and for determining structural capacity obtained from site measurements. (See Jacobs report "VAR9-2932 Assessment Programme – Assessment and Inspection Report – Bridge Ref.: IMD/433"). Vehicle loading obtained from and applied in accordance with BE4. Standard BE4 loading representative of 24 ton vehicles will be assessed.

Codes to be used

BE4 - "The Assessment of Highway Bridges for Construction and Use Vehicles" Ministry of Transport, 1967 (with amendments to 1969).

BS 153: Parts 3B & 4: 1958 "Steel Girder Bridges" British Standards Institution (with amendments to 12 Sept 1968).

## (b) Proposed Method of Structural Analysis

Capacities of the girders will be calculated using estimates of reduced section sizes where corrosion is present. A general condition factor is not applied.

The bridge complies with the construction types listed in BE4 Clause 303 (c) (i.e. Jack arches), which will allow the quick assessment method to be used on the internal girders.

The four internal girders attracting live loading will be checked for full 24 ton C&U loading.

The concrete deck construction offers restraint to the top flanges of the internal girders against lateral torsional buckling; therefore effective length will be taken as zero.

The edge girders are separated from the carriageway by an intervening girder and therefore are not required to be assessed for live loads. They will be checked for dead load effects only. They are partially restrained by the concrete, held by tie-bars and have extra stiffening from the edge angles. Their effective length will be conservatively taken as half their effective span.

Review of the adequacy of the jack arches will be based upon the empirical method described in Bridgeguard 3 Current Information Sheet No 22 (Pro-forma for the empirical assessment of brick, masonry and concrete jack arches and associated ties.)

The abutments will be assessed qualitatively.

**FORM 'AA' (BRIDGES)**

**GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: B (Nov 2000)

**APPROVAL IN PRINCIPLE FOR ASSESSMENT (BE4)**

**Senior Civil Engineer's Comments**


.....  
.....  
**NONE**  
.....  
.....

Proposed Category for Independent Check ..... **1**  
Superstructure ..... **1**  
Substructure ..... **1**  
Name of Checker suggested if Cat 2 or 3 ..... **N/a**

**Category 1**

The above assessment, with amendments

Signed  
Title  
Date



**Category 2 and 3**

The above assessment, with amendments shown, is approved in principle:

Signed .....  
Title ..... **N/a**  
Date .....

Signed .....  
Title ..... **N/a**  
Date .....

**Appendix E Form BA**

**FORM 'BA' (BRIDGES)****GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: A (Dec 2005)

**CERTIFICATION FOR ASSESSMENT CHECK****Assessment Group: Jacobs Engineering UK Ltd****Bridge/Line Name: Mill Tack Road Bridge / Inveramsay to Macduff****Category of Check: 1****ELR/ Bridge No: IMD/433**

We certify that reasonable professional skill and care have been used in the assessment of the above structure with a view to securing that:

- (1) It has been assessed in accordance with the Approval in Principle as recorded on Form AA approved on 10 September 2010.
- (2) It has been checked for compliance with the following principal British Standards, Codes of Practice, BRB (Residuary) Limited technical notes and Assessment standards:

BE4 - "The Assessment of Highway Bridges for Construction and Use Vehicles" Ministry of Transport, 1967 (with amendments to 1969).

BS 153: Parts 3B & 4: 1958 "Steel Girder Bridges" British Standards Institution (with amendments to 12 Sept. 1968).

List any departures from the above and additional methods or criteria adopted, with reference and justification for their acceptance.

None

Category 1

| Name | Signature | Date |
|------|-----------|------|
|      |           |      |

Assessor

Assessment Checker

Authorised signatory of the firm of Consulting Engineers to whom Assessor/Checker is responsible.

**FORM 'BA' (BRIDGES)**

**GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: A (Dec 2005)

**CERTIFICATION FOR ASSESSMENT CHECK**

Category 2 and 3 (Note: Category 1 check must also be signed)

(a) Assessment

Name                      Signature                      Date

Assessor

Assessment Checker

Authorised signatory of the firm of Consulting Engineers to whom Assessor/Checker is responsible.


(b) Check

Name                      Signature                      Date

Assessor

Assessment Checker

Authorised signatory of the firm of consulting engineers to whom Assessor/Checker is responsible.



This Certificate is accepted by .....

**FORM 'BAA' (BRIDGES)****GC/TP0356**

ELR/ Bridge No IMD/433

Appendix: 4

Issue: 1

Revision: A (Dec 2005)

**CERTIFICATION FOR ASSESSMENT CHECK****Notification of Assessment Check**

|                               |                               |
|-------------------------------|-------------------------------|
| <b>Assessment Group</b>       | Jacobs Engineering UK Ltd     |
| <b>Bridge Name/Road No.</b>   | Mill Tack Road / unclassified |
| <b>Line Name</b>              | Inveramsay to Macduff Line    |
| <b>ELR Code/Structure No.</b> | IMD/433                       |

The above bridge has been assessed and checked in accordance with Standards which are listed on the appended Form BA. A summary of the results of the assessment in terms of capacity and restrictions is as follows:-

**STATEMENT OF CAPACITY**

|   |  |
|---|--|
| Main girders carrying carriageway               | Full C&U loading: 24 ton vehicle train |
| Parapet edge girders (No BE4 live load imposed) | Pass                                   |
| Jack arches and ties*                           | Pass                                   |
| Substructure (qualitative assessment)           | Full C&U loading                       |

**Recommended Loading Restrictions**

None.


**Description of Structural Deficiencies and Recommended Strengthening**

The empirical assessment of the jack arches indicates a non-compliance in that the tie bars are located within the crown of the external jack arches. The arch/tie/fill configuration is unlikely to lead to rotation of the edge girders and there are no indications of any movement having occurred. It is therefore concluded that the jack arches and ties are adequate for loading commensurate with the capacity of the girders.

Maintenance painting of the edge girders is recommended.

A coping stone at the west end of the north parapet needs re-setting.

Name \_\_\_\_\_ Signature \_\_\_\_\_ Date \_\_\_\_\_



**Appendix F Calculations**



# CALCULATION COVER SHEET

Jacobs  
Reading

|   |            |  |                 |
|---|------------|--|-----------------|
| Project Title: BRB (Residuary) Ltd - Major Works2009/2012(LISTED BRIDGES) |            | Calc. No.:                                       | 206             |
| Job No: B12360BB  |            | File:  | R17             |
| Project Manager   | [REDACTED] | Subject: <b>IMD/433</b>                          |                 |
| Designer  |            | Mill Tack Road Bridge, Nr Turriff, Aberdeenshire |                 |
| Project Group   |            | 31600  | BE4 Assessments |

|          | Total Sheets | Made by | Date   | Checked by | Date   | Reviewed by | Date |  |  |
|----------|--------------|---------|--------|------------|--------|-------------|------|--|--|
| Original | 11           | CB      | Dec-10 | JR         | Dec-10 |             |      |  |  |
| Rev      |              |         |        |            |        |             |      |  |  |
| Rev      |              |         |        |            |        |             |      |  |  |
| Rev      |              |         |        |            |        |             |      |  |  |
| Rev      |              |         |        |            |        |             |      |  |  |
| Rev      |              |         |        |            |        |             |      |  |  |

|                               |      |
|-------------------------------|------|
| Superseded by Calculation No. | Date |
|-------------------------------|------|


For design criteria, refer to Approval in Principle (Form AA) document

|   |               |                     |
|---|---------------|---------------------|
| Office Reading - Winnersh                                   | Page No. 1    | Cont'n Page No. 206 |
| Job No. B1236000 BRB(R) 2009-12<br>& Title 2011 Assessments | Originator CB | Date 07/12/10       |
| Section IMD-433 Mill Tack Road Bridge                       | Checker gfr   | Date 2/12/10        |

BE4 Assessment of IMD/433 based on Jacobs site survey of July 2010 and the method of structural analysis set out in the Form AA.

Cross Section and Element Dimensions

Jacobs BE4 site survey 07/10




MAIN BEAMS

RSJ sections of 300x300x120.87 kg/m

Section Dimensions

BCSA Historical Structural Steelwork Handbook Table 8.6

mass/ft = 81.22 lbs/ft



Section Properties

BCSA Historical Structural Steelwork Handbook Table 8.6


$I_{xx} = 25759 \text{ cm}^4$        $I_{yy} = 9007 \text{ cm}^4$   
 $r_x = 12.9 \text{ cm}$        $r_y = 7.6 \text{ cm}$   
 $Z_{xx} = 1717 \text{ cm}^3 (104.78 \text{ in}^3)$        $Z_y = 600 \text{ cm}^3$

BE4 pt

concrete self weight = 150 lb/ft<sup>3</sup>

|                   |            |     |                 |          |
|-------------------|------------|-----|-----------------|----------|
| Office            | Page No.   | 2   | Cont'n Page No. | 206      |
| Job No. & Title   | Originator | CB  | Date            | 20/12/10 |
| Section IMD   433 | Checker    | JLR | Date            | 21/12/10 |

calculate modified elastic section modulus ( $Z_{xx}$ ) due to corrosion to lower flange



| Element       | (cm) | (cm) | (cm)           | (cm <sup>2</sup> ) | (cm <sup>3</sup> ) |
|---------------|------|------|----------------|--------------------|--------------------|
|               | $b$  | $d$  | $y$ (from top) | $A$                | $Ay$               |
| top flange    | 30   | 2    | 1              | 60                 | 60                 |
| bottom flange | 30   | 1.9  | 28.95          | 57                 | 1650.15            |
| web           | 1.2  | 26   | 15             | 31.2               | 468                |

total area = 148.2 cm<sup>2</sup>

depth to neutral axis =  $\frac{\sum Ay}{\sum A} = \frac{2178.15}{148.2} = 14.697 \text{ cm}$

| Element       | $A(y-y_i)^2$ | $I = \frac{bd^3}{12}$ (cm <sup>4</sup> ) |
|---------------|--------------|--|
| top flange    | 11256.47     | 20                                       |
| bottom flange | 11579.44     | 17.15                                    |
| web           | 2.86         | 1757.6                                   |
| $\Sigma$      | 22838.77     | 1794.75                                  |

$I_{xxx} = \sum A(y-y_i)^2 + \sum I$   
 $= 24633.52$

$Z_{xx} = \frac{I_{xxx}}{y_i} = \frac{24633.52}{14.697} = 1676.09 \text{ cm}^3$   
 (102.28 in<sup>3</sup>)

$Z_{xt} = \frac{I_{xxx}}{D-y_i} = \frac{24633.52}{30-14.697} = 1609.72 \text{ cm}^3$   
 (98.23 in<sup>3</sup>)


Check:-

| Element                     | Dimension |          | Area            | $y$ from top | $Ay$            | $A(y)^2$        | $\frac{bd^3}{12}$ |
|-----------------------------|-----------|----------|-----------------|--------------|-----------------|-----------------|-------------------|
|                             | $b$ (cm)  | $d$ (cm) | cm <sup>2</sup> | cm           | cm <sup>2</sup> | cm <sup>3</sup> | cm <sup>4</sup>   |
| Top flange                  | 30        | 2        | 60.00           | 1            | 60.00           | 11257.07        | 20.00             |
| Top angles (hor)            | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| Top angles (vert)           | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| Web                         | 1.2       | 26       | 31.20           | 15           | 468.00          | 2.86            | 1757.60           |
| Bottom angles (vert)        | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| Bottom angles (hor)         | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| Bottom flange               | 30        | 1.9      | 57.00           | 28.95        | 1650.15         | 11578.84        | 17.15             |
| Deduct rivets 1 (minus b)   | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| Deduct rivets 2 (minus b)   | 0         | 0        | 0.00            | 0            | 0.00            | 0.00            | 0.00              |
| <b>NET AREA</b>             |           |          | 148.20          |              | 2178.15         |                 |                   |
| <b>GROSS AREA</b>           |           |          | 148.20          |              |                 |                 |                   |
| Depth to Neutral Axis $y_t$ |           |          |                 | 14.70        |                 |                 |                   |
| <b>Sum</b>                  |           |          |                 |              | 22838.77        | 1794.75         |                   |
|                             |           |          |                 |              | $I_{xxx}$       | 24633.52        |                   |
|                             |           |          |                 |              | $Z_{top}$       | 1676.09         |                   |
|                             |           |          |                 |              | $Z_{bot}$       | 1620.35         |                   |

|                 |            |     |                 |          |
|-----------------|------------|-----|-----------------|----------|
| Office          | Page No.   | 3   | Cont'n Page No. | 206      |
| Job No. & Title | Originator | CB  | Date            | 20/12/10 |
| Section         | Checker    | gJR | Date            | 21/12/10 |

Effective Length of Beam ( $l_E$ )

BE4  
CI 303  
(iv)



$$l_E = 15' + (2 \times 0.98'') \\ = 15' 1.96'' \\ = 15.16 \text{ Ft}$$

Permissible Stresses

BE4 Part I Permissive stresses from BS 153, Part 3B, Table 1, CI 304(a) Case II

BS 153 Part 3B Table 1 A (solid web girders), Case II = + 25% increase to allowable stress from CI 25-36

BS 153 Part 3B Table 3 Parts in bending  $9.5 \text{ ton/in}^2 (15.0 \text{ kg/mm}^2) = P_{bt}, P_{bc}$   
Parts in shear  $5.5 \text{ ton/in}^2 (8.7 \text{ kg/mm}^2) = P_q$

BS 153 Part 3B CI 29 Ave shear stress  $< 6 \left[ 1.3 - \frac{b/t}{250 \left( 1 + \frac{1}{2} \left( \frac{b}{a} \right)^2 \right)} \right] \text{ ton/sq.in}$   
where  $a = 300 \text{ mm } (11.811'')$   
 $b = 260 \text{ mm } (10.236'')$   
 $t = 12 \text{ mm } (0.4724'')$

$P_q$  must be  $< 7.42 \text{ ton/in}^2$   
 $\therefore$  Table 3 value applies  $P_q < 5.5 \text{ ton/in}^2$

modified by Table 1

$P_{bt}$  and  $P_{bc} \Rightarrow 9.5 \times 1.25 = 11.875 \text{ ton/in}^2 (13.75 \text{ kg/mm}^2)$   
 $P_q \Rightarrow 5.5 \times 1.25 = 6.875 \text{ ton/in}^2 (10.875 \text{ kg/mm}^2)$

Section Capacity

$M_c = Z_{xt} \times P_{bt}$   
 $= 102.28 \times 11.875$   
 $= 1214.58 \text{ ton.in} = 101.24 \text{ ton.ft}$

$P_q = \text{web area} \times P_q$   
 $= 0.4724 \times 10.236 \times 6.875$   
 $= 33.24 \text{ tons}$

Jacobs  
BE4 site  
survey 07/10

top Flange is restrained against buckling in internal beams  
effective length = 0  $\therefore$  not considered

|                 |            |     |                 |          |
|-----------------|------------|-----|-----------------|----------|
| Office          | Page No.   | 4   | Cont'n Page No. | 206      |
| Job No. & Title | Originator | CB  | Date            | 20/12/10 |
| Section         | Checker    | JJR | Date            | 21/12/10 |

INTERNAL BEAMS

Dead Load Analysis on internal beams

beam self weight

$$81.22 \text{ lbs/ft} = 0.03626 \text{ ton/ft} \quad \checkmark$$

$$\begin{aligned} \text{bending (midspan)} &= \frac{0.03626 \times 15.16^2}{8} \\ &= 1.0417 \text{ ton.ft} \quad \checkmark \end{aligned}$$

$$\begin{aligned} \text{shear (reactions)} &= \frac{0.03626 \times 15.16}{2} \\ &= 0.2749 \text{ tons} \quad \checkmark \end{aligned}$$


concrete jack arch and surfacing self weight

conservatively use concrete self weight and surfacing self weight as 150 lb/ft<sup>3</sup>

cross sectional area of jack arch/surfacing

$$\begin{aligned} \text{total area} &= (99.927 - 99.404) \times 0.915 \\ &= 0.4785 \text{ m}^2 \\ &= 5.1515 \text{ ft}^2 \quad \checkmark \end{aligned}$$

jack arch segment



take 2/3 of square area as estimate  
 $= 0.07497 \text{ m}^2$   
 $= 0.8070 \text{ ft}^2$

$$\text{Area} = 5.1515 - 0.8070 = 4.3445 \text{ ft}^2$$

$$\begin{aligned} \text{dead load} &= 4.3445 \times 150 \\ &= 651.68 \text{ lbs/ft} \\ &= 0.2909 \text{ tons/ft} \end{aligned}$$

$$\begin{aligned} \text{bending (midspan)} &= \frac{0.2909 \times 15.16^2}{8} \\ &= 8.357 \text{ ton.ft} \end{aligned}$$

$$\begin{aligned} \text{shear (reactions)} &= \frac{0.2909 \times 15.16}{2} \\ &= 2.205 \text{ tons} \end{aligned}$$

|                 |            |     |                 |          |
|-----------------|------------|-----|-----------------|----------|
| Office          | Page No.   | 5   | Cont'n Page No. | 206      |
| Job No. & Title | Originator | CB  | Date            | 20/12/10 |
| Section         | Checker    | JZR | Date            | 21/12/10 |

**TOTAL DEAD LOAD EFFECTS**

bending = 9.3987 ton.ft  
 shear = 2.4799 tons

Live Load effects on internal beams

BE4 Part II  
 Section 3  
 Graph 5

inputs  $l_E = 15.16$  ft  
 Gross vehicle weight = 24T

bending (midspan) = 52 ton.ft

BE4 Part II  
 Section 3  
 Graph 1

Proportion Factor (k)

input  $l_E = 15.16$  ft  
 girder spacing = 3ft

$k = 0.28$

**TOTAL LIVE LOAD EFFECT**

bending (midspan) =  $52 \times 0.28$   
 = 14.56 ton.ft

Check beams pass in bending

P3

capacity = 101.24 ton.ft  
 applied =  $9.3987 + 14.56 = 23.96$  ton.ft

$\therefore$  remaining capacity = 77.28 ton.ft

BE4 PII  
 Section 3  
 301(b)

Check beams pass in shear

P3

capacity = 33.24 tons  
 dead load = 2.4799 tons  
 $\therefore$  live load capacity =  $33.24 - 2.4799$   
 = 30.84 tons

BE4 PI  
 305 (a)  
 and Tab 1

$30.84$  tons > 10  $\therefore$  24t vehicle capacity

Internal beams  
 24t vehicle capacity

|                 |            |     |                 |          |
|-----------------|------------|-----|-----------------|----------|
| Office          | Page No.   | 6   | Cont'n Page No. | 206      |
| Job No. & Title | Originator | CB  | Date            | 20/12/10 |
| Section         | Checker    | JLR | Date            | 21/12/10 |

EDGE BEAMS

IMD-433  
BE4  
Form AA

"Edge girders are separated from carriageway by an intervening girder and therefore not required to be assessed for live loads"

$$l_E = \frac{15.16 \text{ ft}}{2} = 7.58 \text{ ft} = 90.96 \text{ in}$$

BS 153  
Part 3B  
C128  
b(i)B

Check compression flange

$$C_s = \frac{170000}{(l_E/r_y)^2} \sqrt{\left(1 + \frac{1}{20} \left(\frac{l_E T}{r_y D}\right)^2\right)} + K_2 \frac{170000}{(l_E/r_y)^2}$$

$$r_y = \sqrt{\frac{I_{yy}}{A}} \quad (\text{calculate to consider corrosion})$$

$$I_{yy} = \frac{2 \times 30^3}{12} + \frac{1.9 \times 30^3}{12} + \frac{26 \times 1.2^3}{12}$$

$$= 8778.74 \text{ cm}^4$$

$$A = (2 \times 30) + (1.9 \times 30) + (26 \times 1.2)$$

$$= 148.2 \text{ cm}^2$$

$$\Rightarrow r_y = \sqrt{\frac{8778.74}{148.2}}$$

$$= 7.696 \text{ cm}$$

$$= 3.030 \text{ in}$$

BS 153  
Part 3B  
Table 5

$$T = K_1 \times 0.7874 \text{ in} \quad \text{where } N=1 \Rightarrow K_1=1$$

$$= 0.7874 \text{ in}$$

$$D = 11.811 \text{ in}$$

BS 153  
Part 3B  
Table 6

$$K_2 = 0.013 \text{ based on } M=0.513$$

$$\text{from } I_{\text{top flange}} = \frac{2 \times 30^3}{12}$$

$$= 4500 \text{ cm}^4$$

$$I_{\text{bottom flange}} = \frac{1.9 \times 30^3}{12}$$

$$= 4275 \text{ cm}^4$$

$$C_s = \frac{170000}{\left(\frac{90.96}{3.03}\right)^2} \sqrt{\left(1 + \frac{1}{20} \left(\frac{90.96 \times 0.7874}{3.03 \times 11.811}\right)^2\right)} + 0.013 \left(\frac{170000}{\left(\frac{90.96}{3.03}\right)^2}\right)$$

$$= 209.12 \text{ ton/in}^2$$

BS 153  
Part 3B  
Table 8

$$p_{bc} = 10 \text{ ton/in}^2 \quad \therefore \text{use } 10 \text{ ton/in}^2 \text{ not that from P3}$$

$$\text{section capacity (compression flange)} =$$

$$Z_{xc} \times p_{bc} = 102.28 \times 10$$

$$= 1022.8 \text{ ton.in}$$

$$= 85.23 \text{ ton.ft}$$

|                    |            |     |                 |          |
|--------------------|------------|-----|-----------------|----------|
| Office             | Page No.   | 7   | Cont'n Page No. | 206      |
| Job No. & Title    | Originator | CB  | Date            | 20/12/10 |
| Section<br>IMD/433 | Checker    | JJR | Date            | 21/12/10 |

Dead load effects

P4

beam self weight  $\Rightarrow 1.0417 \text{ ton.ft}$   
 concrete + macadam self weight =  $\frac{8.0525}{2}$   
 $= 4.0263 \text{ ton.ft}$   
 parapet self weight, allow  $25 \text{ lbs./ft}$   
 bending (midspan) =  $\frac{25 \times 15.16^2}{8}$   
 $= 718.21 \text{ lbs.ft}$   
 $= 0.321 \text{ ton.ft}$

**TOTAL DEAD LOAD EFFECT**  
 $= 1.0417 + 4.0263 + 0.321$   
 $= 5.389 \text{ ton.ft} < 85.23 \text{ ton.ft}$

Edge beams with required BE4 capacity

$\therefore$  PASS

tension due to bending in lower flange and shear in web are less onerous in edge beams than internal beams due to lower dead load effects and no live load effects  $\therefore$  no calculations required.

JACK ARCH ASSESSMENT

IMD-433  
Form AA

Empirical assessment using Bridgeguard 3 Current Information Sheet No. 22

see appended Bridgeguard Proforma for Empirical Assessment of Brick, Masonry and Concrete Jack Arches.

Non-compliant / Failing elements

\* Possible failure due to tie bar location at crown of jack arches

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

|  |
|--|
| BRIDGE NAME: IMD-433 Mill Tack Road Bridge |
| RAILTRACK NO:                              |

Jack Arch Assessment

Assessment should include completion of all three Sections even where Section 1 has shown the bridge deck to be non-compliant.

SECTION 1 CHECKS FOR COMPLIANCE WITH 40 T CONFIGURATION REQUIREMENTS

|   | Compliant<br>Yes/No  |
|---|--|
| What is maximum clear span of the arch<br><i>Non-compliant if greater than 2.0m.</i>  | m<br>Yes   |
| Do jack arches spring from bottom flanges of beams?<br><i>If not, non compliant</i>   | Yes<br>Yes   |
| What is the beam spacing?<br>What is the rise of the arch?<br>Gross aspect ratio  | b = 0.915<br>r <sub>c</sub> = 0.147<br>b/r <sub>c</sub> = 6.22<br>m<br>m<br>Yes<br><i>Non-compliant if greater than 10</i> |
| What is the arch barrel thickness (including concrete fill above) and how is it derived i.e. from record drawings or site investigation?<br><i>Non-compliant if thickness less than 220</i> | d =<br>mm<br>N/A   |

JLR.  
21/12/10

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

BRIDGE NAME: IMD-433 Mill Tack Road Bridge

RAILTRACK NO:

SECTION 2 CHECKS FOR DEFICIENCY

| Type No | Deficiency   | Pass/Fail               |
|---------|--|-------------------------|
| 1       | <p>What is the backing material? Is it structural? <i>concrete?</i></p> <p>Does the structural backing extend to at least the crown level of the arch extrados?<br/><i>If not, then fail<sup>(1)</sup> (4).</i></p> <p>What is effective shear depth of deck?<br/>(= arch rise + barrel thickness + height of structural fill above crown of extrados)<br/><i>D<sub>s</sub> 366 = mm<br/>minimum = 310mm</i></p> <p>Is D<sub>s</sub> ≥ minimum requirements of Fig 1. Fail if &lt; Fig 1</p> | <p>Pass</p> <p>Pass</p> |
| 2       | <p>Do jack arches span longitudinally (eg in half through girder construction) or transversely between longitudinal girders? <i>transversely</i></p> <p>For longitudinal spanning jack arches, ignore following questions on ties/lateral restraint and state N/A.</p> <p>Are ties provided in edge bays of transversely spanning jack arches? <i>Yes</i></p> <p><i>If yes, go to 3a/3b</i> <i>If not, fail unless edge bay is 'hard' (see 5)</i></p>  | <p>Pass</p>             |
| 3a      | <p>What is the cross sectional area of one tie? (allowing for corrosion losses) A = mm<sup>2</sup></p>   |                         |
| CI      | <p>What is number of ties per beam length? n = No</p> <p>What is the clear skew span? L = m</p> <p>Specific area of tie (A<sub>s</sub>) = <math>\frac{(n+1) \times A}{L}</math> A<sub>s</sub> = mm<sup>2</sup>/m</p> <p><i>Non-compliant if less than 260mm<sup>2</sup>/m.</i></p> <p>What is maximum tie spacing? S = m</p> <p><i>Non-compliant if greater than 2.5m for cast iron</i></p>  |                         |
| 3b      | <p>What is the cross-sectional area of one tie? (allowing for corrosion losses) A = 506.71 mm<sup>2</sup><br/><i>assume 1in bar = 25.4mm φ</i></p>   |                         |
| WI/ST   | <p>What is number of ties per beam length? n = 2 No</p> <p>What is the clear skew span? L = 4.621 m</p> <p>Specific area of tie (A<sub>s</sub>) = <math>\frac{(n+1) \times A}{L}</math> A<sub>s</sub> = 328.96 mm<sup>2</sup>/m</p> <p><i>Non-compliant if less than 260mm<sup>2</sup>/m</i></p> <p>What is maximum tie spacing? S = 1.524 m</p> <p><i>Non-compliant if greater than 3.0m for wrought iron/steel</i></p>   | <p>Pass</p> <p>Pass</p> |
| 4       | <p>Are ties located within crown of external arch? <i>Yes</i></p> <p><i>If so, then fail CI or possible fail for WI/ Steel</i></p>   | <p>Pass</p> <p>Fail</p> |
| 5       | <p>Does external bay construction provide alternative lateral restraint? (ie not soft edge)?</p> <p><i>If so, pass.</i></p> <p><i>If not, are ties provided in first Jack Arch bay? If yes, treat as 3a (or 3b). Otherwise fail.</i></p>   |                         |

Notes: (1) Results also in loss of D/d (composite action) for cast iron beams

(4) A trial hole should be undertaken to confirm the existence of structural backing if there is any doubt.

*JLR*  
*21/12/10*

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK ARCHES AND ASSOCIATED TIES

(To be included with the Assessment Report Calculations)

|  |
|--|
| BRIDGE NAME: 14D-433 Mill Tack Road Bridge |
| RAILTRACK NO:                              |

SECTION 3 CHECKS FOR DEFECTS

| Type No | Defect  | Empirical Assessment |   | Pass /Fail |
|---------|---|----------------------|---|------------|
|         |   | CI Decks             | WI/Steel Decks  |            |
| 6       | Rotation of supporting beam   | Fail                 | Fail  | Pass       |
| 7       | Horizontal displacement of supporting beam  | Fail                 | Fail displacement of adjacent parapet stone appears unrelated                       | Pass       |
| 8       | Inadequate support to springings eg corrosion of bottom flange of supporting beam over a significant length, missing bedding mortar | Possible Fail        | Possible Fail corrosion to lower flange is not to significant depth i.e. 5% maximum | Pass       |
| 9       | Transversely bowed bottom flange of supporting beam   | Fail                 | Fail none reported  | Pass       |
| 10      | Cracking at crown of arch owing to spreading of springings (other than 12, 13)  | Fail                 | Fail none reported  | Pass       |
| 11      | Distortion and any associated cracking of jack arch barrel  | Fail                 | Fail none reported  | Pass       |
| 12      | Arch crack resulting in substructure crack  | Fail                 | Fail (5)  | Pass       |
| 13      | Substructure crack or other distress resulting in crack to jack arch  | Possible Fail (3)    | Possible Fail (3) (5)   | Pass       |


Note: (3) 'Substructure renovation' or 'Monitoring' as appropriate; 'Repair of arch' (if appropriate).  
 (5) Not applicable in general to longitudinally spanning arches.

JAR  
 21/12/10

PRO FORMA FOR EMPIRICAL ASSESSMENT OF BRICK, MASONRY AND CONCRETE JACK  
ARCHES AND ASSOCIATED TIES  
(To be included with the Assessment Report Calculations)

BRIDGE NAME: 1HD-433 Mill Tack Road Bridge


RAILTRACK NO:



\* (= arch rise + barrel thickness + height of structural fill above crown of extrados)

Figure 1

JZR  
21/12/10



IMD/433

